

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	NTUC INCOME IN:	SURANCE CO-OPERATIVE LTD	Ref:	CS/INC21005179/Gqf3e2	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE	Date	e: 11/06/2021	
	ATTN: DAVID PHU	JA .	Cod	le: INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLX 1849T	Veh. Inspected	FBJ 4846Z	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1129439-002	Excess (\$)	0.00	
	Assign From	THERESA VIMALA	Assign Date	27/04/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	K.T.M. 200 DUKE	c.c	200	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	VBKJUC40XEC009958	Colour	WHITE / BLACK	
	Odometer	75173 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	110/70 R17	BRIDGESTONE	4 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	150/60 R17	BRIDGESTONE	4 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DI	ETAILS.			
5.	General Information				
	Accident Date	14/04/2021	Inspect Date / Time	27/04/2021 (12:00 PM)	
	Survey held at	DIRT WHEEL MOTOR TRADING	3		
		BLK 9004 #01-100 TAMPINES ST 93 SINGAPORE 528838			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			