

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21005181/KQF3E2
Date: 25/05/2021

REFERENCE

Insured/Claimant: LIAN TAT (JACK) ENGINEERING PTE LTD Policy No: DMCVSNW00060492000
Date of Loss: 22/04/2021 Nature of Claim: OD Claim No: SNM21D202356/C01/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD9805R**
Make & Model: NISSAN CABSTAR, 3.0 (M) Engine No: ZD30346765K
Reg. Date: 05/08/2015 (Man. Year: 2015) Chassis No: JN1SC2F24Z0857239
Colour: Silver Odometer: 193975 km
Engine Capacity: 2953 cc
Market Value/New Car Price: S\$38,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 155 R12X8 (D)
Front Left Side: Rovelov 8 mm Rear Left Side: Maxxis 8/8 mm
Front Right Side: Rovelov 8 mm Rear Right Side: Maxxis 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,141.00	1,888.00	1,253.00	39.89
Miscellaneous Items	30.00	30.00	0.00	0.00
Labour	1,477.03	634.60	842.43	57.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,648.03	2,552.60	2,095.43	45.08
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	4,648.03	2,052.60	2,595.43	55.84
Nett Amount (S\$)	4,973.39	2,196.28	2,777.11	55.84

INSPECTION

Date of Assignment: 27/04/2021
Date Inspected: 28/04/2021 Inspected At: BLK 5035 AMK INDUSTRIAL PARK 2 #01-367
Estimated Period of Repair: 4.0 days Repairer: Goldbell Engineering Pte Ltd

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 May 2021)	
Parts:	N/A	NISSAN CABSTAR 3.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD9805R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Total Parts		3,043.00 F	*1,790.00 F
<u>Supplementary #1</u>						
2	1		*RH FRONT DOOR STEP GARNISH	Cracked	98.00 F	*98.00 F
F=Franchise part.						
Total Parts (S\$)					3,141.00	1,888.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Total Of Extras	30.00	30.00
Sub Total (\$\$)			30.00	30.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total of Labour	New	898.80	243.60
2	Total Paint Including Material	New	578.23	391.00
Gross Labour Cost (\$\$)			1,477.03	634.60

Report was unsubmitted during this print-out.

< END OF ESTIMATES >