

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI21005182/GUF3E2

**Date:** 22/06/2021

### REFERENCE

Insured/Claimant: ZHOU YUYAN Policy No: DMPCSNW00024202000  
Date of Loss: 22/04/2021 Nature of Claim: OD Claim No: SNM21D202389/C01/TAYHP

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMS6311J**  
Make & Model: HONDA SHUTTLE, 1.5 G CVT (A) Engine No: L15B6024672  
Reg. Date: 05/03/2020 (Man. Year: 2019) Chassis No: GK82104028  
Colour: White Odometer: 37891 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: S\$84,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,139.00	6,238.00	1,901.00	23.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	821.43	770.75	50.68	6.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>8,960.43</b>	<b>7,008.75</b>	<b>1,951.68</b>	<b>21.78</b>
<b>+ GST 7.00/7.00% (S\$)</b>	627.23	490.61	136.62	21.78
<b>Nett Amount (S\$)</b>	<b>9,587.66</b>	<b>7,499.36</b>	<b>2,088.30</b>	<b>21.78</b>

### INSPECTION

Date of Assignment: 27/04/2021

Date Inspected: 27/04/2021 Inspected At:

53 Ubi Ave 1 #01-34

Repairer: Goldbell Engineering Pte Ltd

Estimated Period of Repair: 5.0 days

**Adjuster:** XING GUO QIANG

**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 22 Jun 2021)	
<b>Parts:</b>	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMS6311J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*Total Parts</b>		6,416.00 F	*4,440.00 F
<b><u>Supplementary #1</u></b>						
2	1		<b>*BONNET STAND CLIP</b>	Necessary	9.00 F	*9.00 F
3	1		<b>*COVER L. HOOD</b>	Deformed	30.00 F	*30.00 F
4	1		<b>*RADAR SUB ASSY</b>	Not Working	782.00 F	*782.00 F
5	1		<b>*RUBBER BONNET</b>	Twisted	50.00 F	*50.00 F
6	1		<b>*RADAR BRACKET</b>	Bent	300.00 F	*300.00 F
7	1		<b>*PIPE COMP, RADAR</b>	Bent	50.00 F	*50.00 F
8	1		<b>*STAY FRONT GRILLE</b>	Broken	65.00 F	*140.00 F
<b><u>Supplementary #2</u></b>						
9	1		<b>*FRONT PANEL CPL</b>	Bent	437.00 F	*437.00 F
F=Franchise part.						
<b>Total Parts (S\$)</b>					<b>8,139.00</b>	<b>6,238.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	Total of Labour	New	315.00	348.60
2	Total Paint Including Material	New	506.43	422.15
<b>Gross Labour Cost (S\$)</b>			<b>821.43</b>	<b>770.75</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >