

ASS. REC. BY: *kel*

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: **SMS 6311J**
 at Workshop n/s: **Goldbell Engineering**
 of _____
 Insured: _____
 Policy No: **DMPCSNW00024202000**
 Claims No: **SNM21D202389/C01**
 Sum Insured: _____ Excess: **FBA 0/-**
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: **\$84K**
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **5** days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / **REV** / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SMS 6311J** Yr Regn: **05 Mar 2020**
 Type: **M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**
 Truck / Trailer or **1.5G**
 Make: **Handy Shuttle** C.C. **1496**
 Colour: **white** A/C: **Insured / Std / NI / NA**
 Sp. Reading: **3789.1** T/Radio: **Insured / Std / NI / NA**
 Eng/No: _____
 C/No: **GK 8264028**
 Gen. Cond: **Good / Fair / Poor / Burnt**
 Steering: **In Order / Jammed / Leaked / Burnt or**
 Brake: **In Order / Jammed / Leaked / Burnt or**
 Modi: **NR / S/Rim / STD A/Rim or**
 Tyre Size: F: **185/60 R15**
 R: **17**
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. **6** mm R/Bal. **6** mm
 L/Bal. **6** mm L/Bal. **6** mm
 D.O.A. _____ D.O.I. **27-04-21**
 Survey held at **W/S** **11AM**
 Des. of Damages: **Frt** / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
28/4/2021 @ 2.10pm	Revert to Irene Tay via Merimen.
30/4/2021 @ 12.54pm	Irene Tay informed C/A via Merimen.
30/4/2021 @ 2.52pm	Informed Catherine C/A & ex:\$0/- by email.
21/6/2021 @ 4.05pm	Confirm final fig with Catherine P/P \$7008.75, 5 repair days. (RED \$2026.68; 22%)

Date/Time, File Pass to?

☐ : Preli. Report

1) 21/6 TYPIST

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: **5**Resurvey No. of Trip: **1**Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : Misc (\$

Survey Fee:

Transportation:

S + RS \$1

Photos

Other:

Report Found: **MER-OD**
\$7008.75

Goldbell Engineering Pte Ltd
8 Tuas Ave 18, Singapore
638892

Insurer Reference: SMS6311J
Repairer Reference: 040881
Date calculated: 26/04/2021 3:31 PM

Full Report
Registration: SMS6311J
Printed: 26/04/2021 3:31 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Catherine Chong Kai Ling	Currency:	SGD
Claim Reference:	SMS6311J	Date of Incident:	22/04/21
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	JAZZ (GK3/GK5/GK7)
Sub Model:	BASE MODEL
Model Sheet Number:	35 CK 01
Registration:	SMS6311J
VIN number:	GK82104028
Odometer:	37890

Model Specs

AIR CONDITIONING	1.5 LTR 88KW	TWO COAT METALLIC	PREPARE OFF VEHICLE
------------------	--------------	-------------------	---------------------


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 42.00 SGD/h

	Description	WU	Price SGD
LA2	RENEW FRONT BUMPER	9.0	37.80
	INCLUDES: R + R NECESSARY ATTACHED PARTS		
101B1)	R + R FRONT BUMPER SUPPORT	1.0	4.20
812100	RENEW BONNET	10.0	42.00
	INCLUDES: R + R BONNET AND		
	REQUIRED ATTACHED PARTS ASSEMBLE		
812105	R + R WINDOW FRAME GRILLE	3.0	12.60
812120	R + R BONNET LOCK	2.0	8.40
NO NUMBER	R + R BONNET STAY	1.0	4.20
NO NUMBER	R + R TOWING EYE COVER	1.0	4.20
NO NUMBER	RENEW L/FRT WING	5.0	21.00
	INCLUDES: L/F WING AND REQUIRED		
	ATTACHED PARTS R + R		
8121B6)	R + R L/BONNET HINGE	1.0	4.20
7221A0)	R + R LEFT HEADLAMP	4.0	16.80
NO NUMBER	RENEW R/FRT WING	5.0	21.00
	INCLUDES: R/F WING AND REQUIRED		
	ATTACHED PARTS R + R		
8121B7)	R + R R/BONNET HINGE	1.0	4.20
7221B6)	R + R RIGHT HEADLAMP	4.0	16.80
620020	DRAIN/REFILL AIR CONDITIONING	7.0	29.40
114100)	R + R RADIATOR	14.0	58.80
1211D5	R + R AIR FILTER HOUSING	4.0	16.80
616100)	R + R AIR CONDITIONING CONDENSER	3.0	12.60
Labour Cost		Hrs	WU
Panel / Mechanical Labour		7.50	75.0
Total of Labour			315.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU	Price SGD
	BONNET NEW PART PAINTING	16.0	
	L/F WING NEW PART PAINTING	10.0	
	R/F WING NEW PART PAINTING	10.0	
	FRONT BUMPER NEW PART PAINT K1R	12.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	46.96
0741	L/F WING NEW PART PAINTING	19.09
0742	R/F WING NEW PART PAINTING	19.09
0283	FRONT BUMPER NEW PART PAINT K1R	56.09

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			
Time Paint			
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	78.0	327.60

Material Cost - Paint

	Price SGD
New Part Painting	85.14
New Part Painting - Plastic K1R	56.09
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	178.83

Spare Parts

prices as at 2015-06-01/01				
Code	Description	Part Number	Part Source	Price SGD
0257	FRONT NUMBER PLATE	X KNPL3	Original	25.00
0283	✓ FRONT BUMPER	71101T5LT10ZZ	Original	680 610.00 ✓
0293	FRT TOWING EYE COVER	71104T5ZQ00ZB	Original	15.00
0319	✓ L/F HEADLAMP BRACKET	71190T5A000	Original BR	55 40.00 ✓
0320	R/F HEADLAMP BRACKET	71140T5LT00	Original NN	40.00
0340	FRT BUMPER SUPPORT	71130T5LT00ZZ	Original NN	370.00
0343	FRONT BUMPER SPOILER	71110T5A000	Original NN	80.00
0351	FRT LWR BUMP GRILLE	71102T5A000	Original NN	0.00
0410	✓ GRILLE	71121T5ZQ10	Original	230 161.00 ✓
0412	✓ RAD GRILLE COVER	71123T5NM00	Original	315 190.00 ✓
0431	✓ GRILLE BADGE	75700TA0A00	Original	300 0.00 ✓
0432	✓ RAD GRILLE BRACKET	71124T5LT00	Original BT	65 0.00 ✓
0433	✓ UP/CVR RADIAT GRILLE	71105T5A000	Original DE	65 50.00 ✓
0471	✓ BONNET	60100T5LT00ZZ	Original	530 500.00 ✓
0475	✓ L/BONNET HINGE	60170T5A000ZZ	Original ✓ BT	35 20.00 ✓
0476	R/BONNET HINGE	60120T5A000ZZ	Original X NN	20.00
0481	BONNET INSULATION	4141T5LT00	Original X NN	0.00
0492	✓ BONNET LOCK	74120T5A003	Original	95 85.00 ✓
0495	BONNET STAY	74145T5A000	Original	0.00
0561	✓ L/F HEADLAMP	33150T5AT01	Original BR	483 1,400.00 ✓
0562	✓ R/F HEADLAMP	33100T5AT01	Original BR	483 1,400.00 ✓
0643	L/F BUMPER COVER	71108T5A000	Original	30.00
0644	R/F BUMPER COVER	71103T5A000	Original	30.00
0741	L/F WING	60261T5HH00ZZ	Original	160.00
0742	R/F WING	60211T5HH00ZZ	Original	160.00
4465	✓ CONDENSER	80100T5LP01	Original BT	667 600.00 ✓
7761	✓ RADIATOR	190105V3Q01	Original BT	437 430.00 ✓
f: OEM Parts				0.00
n: Non-OEM Parts				6,416.00
u: Used parts				
Savings				0.00
Subtotal				6,416.00
Total				6,416.00

Calculation

	SGD	SGD
Parts		
Total Parts	6,416.00	6,416.00
Labour Time Base 10 WU/h		
Total 75.0 WU X 42.00 SGD/h	315.00	315.00
Total of Labour		
Paint Work Time Base 10 WU/h		
Labour Cost 78.0 WU X 42.00 SGD/h	327.60	
Material Cost	178.83	506.43
Total Paint Including Material		
Repair Cost Excludes GST		7,237.43
GST (+7.0%)		506.62
Repair Cost Included GST		7,744.05

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

5 4 Days .

P/P

before paint photos .

Geo Q: ang - 8288 0282

27/4/21

Gross : TRA

Not Authorized .

LKR Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: