

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005185/GGA3Q2
Date: 08/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900098730
Claimant Vehicle No :	SMC3952M	Insured Vehicle No :	SFL9833U
Date of Loss:	20/04/2021	Nature of Claim:	TP
		Claim No:	4970488313SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC3952M	Engine No:	2ZR2A00217
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Chassis No:	ZYX102125027
Reg. Date:	29/06/2018 (Man. Year: 2018)	Odometer:	81296 km
Colour:	Yellow		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,156.00	703.75	2,452.25	77.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,060.00	990.00	48.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,206.00	1,763.75	3,442.25	66.12
Approved Total (Overridden) (S\$)		1,400.00		

(S\$)	5,206.00	1,400.00	3,806.00	73.11
+ GST 7.00/7.00% (S\$)	364.42	98.00	266.42	73.11
Nett Amount (S\$)	5,570.42	1,498.00	4,072.42	73.11
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,800.00		

INSPECTION

Date of Assignment: 27/04/2021

Date Inspected: 28/04/2021

Estimated Period of Repair: 3.0 days

Inspected At: Connect3 (HQ)
566 Woodlands Road
Singapore 728697

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH PASSENGER DOOR	Repair	1,410.00 F	*- FL
2	1		*REAR RH PASSENGER DOOR LOWER PROTECTOR	Scratched	285.00 F	*285.00 FL
3	1		*REAR RH PASSENGER DOOR GLASS OUTER MOULDING	Not Necessary	166.00 F	*- FL
4	1		*REAR RH PASSENGER DOOR FRAME STICKER	Necessary	73.00 F	*73.00 FL
5	1		*REAR RH PASSENGER DOOR INNER RUBBER	Not Necessary	180.00 F	*- FL
6	1		*REAR RH FENDER ARCH GARNISH	Scratched	207.00 F	*207.00 FL
7	1		*SET BODY FAIRINGS	Necessary	600.00 FS	*200.00 FS
8	1		*REAR RH PASSENGER DOOR VISOR	Necessary	80.00 FS	*60.00 FS
9	1		*RUBBER BEADING	Not Necessary	15.00 FS	*- FS
10	1		*REAR RH PASSENGER EMBLEM	Necessary	140.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,156.00	845.00
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	141.25
Total Parts (\$\$)	3,156.00	703.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIT REAR RH PASSENGER DOOR MECHANISM	New	150.00	60.00
2	RUST PROOFING	New	100.00	0.00
3	LABOUR CHARGES	New	900.00	400.00
4	SPRAY PAINTING	New	900.00	600.00
Gross Labour Cost (\$\$)			2,050.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >