

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21005189/APA3Q2
Date: 08/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MCV0001894_02
Claimant Vehicle No :	SLG1245A	Insured Vehicle No :	GBA6644Z
Date of Loss:	25/04/2021	Nature of Claim:	TP
		Claim No:	MCV2021D0001792

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG1245A		
Make & Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Engine No:	P520369703
Reg. Date:	21/09/2016 (Man. Year: 2016)	Chassis No:	JM6BM42A8G0343660
Colour:	Grey	Odometer:	191668 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,723.20	3,761.52	3,961.68	51.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,140.00	1,860.00	2,280.00	55.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,863.20	5,621.52	6,241.68	52.61
Approved Total (Overridden) (S\$)		4,500.00		

Nett Amount (S\$)	11,863.20	4,500.00	7,363.20	62.07
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,867.45		
Global Sum Settlement (S\$)		4,800.00		

INSPECTION

Date of Assignment: 27/04/2021

Date Inspected: 28/04/2021

Inspected At:

Ishare Auto Pte. Ltd. (HQ)
 8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT
 Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2021)
Parts:	143	MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG1245A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	998.10 FL	*998.10 FL
2	2		*REAR BUMPER REFLECTOR	Not Necessary	179.60 FL	*- FL
3	2		*REAR BUMPER TOW HOOK COVER	Not Necessary	36.00 FL	*- FL
4	2		*REAR BUMPER LOWER CORNER GARNISH	Not Necessary	95.20 FL	*- FL
5	2		*REAR BUMPER SIDE RETAINER	Necessary	106.60 FL	*106.60 FL
6	1		*REAR BUMPER CENTER BRACKET	Not Necessary	196.80 FL	*- FL
7	1		*TAIL LAMP	O/S Cut	956.60 FL	*478.30 FL
8	2		*TAIL LAMP PANEL	Not Necessary	568.20 FL	*- FL
9	2		*REAR FENDER INNER TRIM	Not Necessary	437.40 FL	*- FL
10	2		*REAR FENDER INNER COWLING	Not Necessary	284.40 FL	*- FL
11	1		*BOOT LID	Buckled	889.60 FL	*889.60 FL
12	2		*BOOT LID NUMBER PLATE LAMP	Not Necessary	95.60 FL	*- FL
13	1		*BOOT LID LAMP	O/S Cut	492.20 FL	*246.10 FL
14	1		*BOOT LID LOGO	Necessary	69.00 FL	*69.00 FL
15	1		*BOOT LID EMBLEM MAZDA 3	Necessary	49.50 FL	*49.50 FL
16	1		*BOOT LID EMBLEM SKYACTIV TECHNOLOGY	Necessary	59.60 FL	*59.60 FL
17	1		*BOOT LID INSULATOR	Not Necessary	246.10 FL	*- FL
18	1		*BOOT LID INNER HOLDER	Not Necessary	63.40 FL	*- FL
19	4		*BOOT LID STOPPER (UPPER)	Not Necessary	80.00 FL	*- FL
20	1		*BOOT LID TOP LOCK	Damaged	142.50 FL	*142.50 FL
21	1		*BOOT LID OUTER SWITCH BUTTOM	Not Necessary	189.10 FL	*- FL
22	1		*BOOT LID OUTER SWITCH BUTTOM SIDE COVER GARNISH	Not Necessary	19.60 FL	*- FL
23	1		*BOOT LID LOWER LOCK	Not Necessary	25.10 FL	*- FL
24	1		*BOOT LID WEATHERSTRIP	Cut	128.70 FL	*128.70 FL
25	2		*BOOT LID HINGE	Not Necessary	128.00 FL	*- FL
26	2		*BOOT LID HINGE COVER GARNISH	Not Necessary	144.40 FL	*- FL
27	1		*REAR END PANEL	Dented	469.70 FL	*469.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR END PANEL TOP GARNISH	Deformed	114.60 FL	*114.60 FL
29	2		*REAR FLOOR PANEL SPONGE	Cracked	651.20 FL	*325.60 FL
30	1		*REAR FLOOR PANEL TOP BOARD	Deformed	374.70 FL	*249.00 FL
31	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
32	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
33	1		*SET REAR BUMPER LOWER CORNER GARNISH CLIP	Not Necessary	60.00 FS	*- FS
34	1		*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
35	2		*TAIL LAMP PANEL SEALANT	Not Necessary	120.00 FS	*- FS
36	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	80.00 FS	*- FS
37	1		*SET BOOT LID OUTER SWITCH BUTTOM SIDE COVER GARNISH CLIP	Not Necessary	60.00 FS	*- FS
38	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
39	1		*SET REAR FENDER COWLING CLIPS	Not Necessary	80.00 FS	*- FS
40	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
41	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
42	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,381.50	4,626.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,658.30	865.38
Total Parts (\$\$)	7,723.20	3,761.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING REMOVAL AND REPLACING PARTS	New	1,400.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	120.00	50.00
7	TRANSFER BOOTLID MECHANISM	New	80.00	60.00
8	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	280.00	0.00
Gross Labour Cost (\$\$)			4,140.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >