



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2201539

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 18/03/2022
Reference CC6/CTI21005190/Dea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 7104Y
Insured Veh. GX 3277P
Claim No. SNM21D202401/C02
Policy No. DMCVSNW00026542100
Accident Date 24/04/2021
Inspection Date 28/04/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21005190/Dea3q2 Date: 18/03/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GX 3277P	Veh. Inspected	SHD 7104Y	
Policy No.	DMCVSNW00026542100	Coverage (\$)	0.00	
Claim No.	SNM21D202401/C02	Excess (\$)	0.00	
Assign From		Assign Date	28/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDKB3FU103537537	Colour	BLUE	
Odometer	734071 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/60 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/60 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/60 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/04/2021	Inspection Date	28/04/2021	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 7104Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	BENT / DENTED	950.50	950.50
1	BONNET HINGE (LH)	BENT	87.70	87.70
1	RADIATOR GRILLE	MTG DEFORMED	438.00	438.00
1	RADIATOR GRILLE EMBLEM	SERVICEABLE	88.00	-
1	FRONT BUMPER COVER	TORN	499.90	499.90
1	FRONT SIDE MEMBER SIDE COVER	NOT NECESSARY	172.50	-
1	FRONT BUMPER SPONGE	TORN	78.80	78.80
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	166.90	-
1	LAMP ASSY ,FOG, LH	DISLODGE / BROKEN	920.00	920.00
1	FRONT BUMPER SIDE RETAINER (N/S)	BROKEN	77.00	77.00
1	FRONT UNDER COVER	NOT NECESSARY	180.80	-
1	FRONT BUMPER TOP GARNISH	NOT NECESSARY	225.40	-
1	COVER,FRONT BUMPER HOLE ,LH	TO REPAIR SEE LABOUR / SERVICEABLE	28.38	-
1	UNIT ASSY ,HEADLAMP ,LH (LED)	BROKEN	3,455.00	2,637.60
1	HEADLAMP ECU	MTG BROKEN	682.60	682.60
1	HEAD LAMP PANEL (LH)	TO REPAIR SEE LABOUR	240.10	-
1	TOP PANEL CENTRE	BENT	364.98	364.98
1	TOP PANEL SIDE	BENT / DENTED	145.90	145.90
1	RADIATOR ASSY	NOT NECESSARY	1,841.80	-
1	RADIATOR FAN GRILLE	NOT NECESSARY	632.40	-
1	GUIDE RADIATOR AIR NO.3	NOT NECESSARY	299.70	-
1	DEFLECTOR ,RADIATOR SIDE ,LH	NOT NECESSARY	83.50	-
1	STAY ,RADIATOR SUPPORT ,LH	NOT NECESSARY	65.70	-
1	RADIATOR FAN BLADE (LH)	NOT NECESSARY	233.10	-
1	RADIATOR FAN MOTOR (LH)	NOT NECESSARY	543.70	-
1	RADIATOR FAN COWLING (LH)	NOT NECESSARY	451.30	-
1	CONDENSER ASSY ,W/RECEIVER	NOT NECESSARY	1,336.60	-
1	FENDER SUB-ASSY ,FRONT LH	DENTED	945.30	945.30

Report Ref No. CC6/CTI21005190/Dea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT HOUSING ASSY	TO REPAIR SEE LABOUR	958.30	-
1	FRONT FENDER SHIELD	DEFORMED / TORN	38.00	38.00
1	FRONT FENDER SHIELD CLIP	NECESSARY	14.90	14.90
1	FRONT FENDER HYBRID EMBLEM ,LH	NECESSARY	86.50	86.50
1	BRACKET ,FRONT SIDE PANEL ,LH	BENT / DENTED	86.30	86.30
1	FRONT WINDSCREEN SIDE GARNISH	DISLODGE	186.40	186.40
1	FRONT BUMPER REINFORCEMENT (ADDITIONAL)	BENT / DENTED	696.40	696.40
1	UNIT ASSY ,HEADLAMP ,RH (LED) (ADDITIONAL)	MTG BROKEN	3,455.00	2,637.60
1	FRONT WINDSCREEN GLASS (ADDITIONAL)	CRACKED	1,627.30	1,627.30
1	FRONT WINDSCREEN GLASS MOULDING (ADDITIONAL)	NECESSARY	208.60	208.60
1	FRONT WINDSCREEN GLASS MOULDING LOWER (ADDITIONAL)	NECESSARY	208.60	208.60
1	FRONT WHEEL RIM (ADDITIONAL)	DISTORTED	1,570.55	1,555.00
1	FRONT WHEEL RIM CAP (ADDITIONAL)	DISTORTED / BENT	189.60	189.60
	LESS 20% DISCOUNT		-4,912.40	-
	LESS 25% DISCOUNT		-	-3,840.87
			19,649.61	11,522.61
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR COMFORT LOGO (SN)	NOT NECESSARY	120.00	-
1	COOLANT (SN)	NOT NECESSARY	45.00	-
2	FRONT WINDSCREEN SEALANT @\$60.00 (SN) (ADDITIONAL)	NECESSARY	120.00	40.00
1	FRONT TYRE (LH) (50%) (SN) (ADDITIONAL)	CUT	216.00	108.00
			501.00	148.00
	<u>LABOUR</u>			
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF COVER,FRONT BUMPER HOLE ,LH ,HEAD LAMP PANEL (LH) AND FRONT HOUSING ASSY .		1,600.00	800.00
	SPRAY PAINTING CHARGE.		1,400.00	700.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX RADIATOR .	NOT NECESSARY	90.00	-

Report Ref No. CC6/CTI21005190/Dea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	130.00	-
	REMOVE /REFIX FUSE BOX.	NOT NECESSARY	120.00	-
	REMOVE/REFIX ENGINE .	NOT NECESSARY	600.00	-
	REMOVE/REFIX DASHBOARD.	NOT NECESSARY	350.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	550.00	150.00
			5,120.00	1,720.00
GRAND TOTAL			25,270.61	13,390.61
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,700.00

Report Ref No. CC6/CTI21005190/Dea3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 7104Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 7104Y

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 7104Y

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

