



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDT 172J

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---------------------------------------|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | REAR BUMPER | CRACKED | 1,846.00 | 1,780.00 |
| 2 | REAR BUMPER SIDE RETAINER | SERVICEABLE | 136.00 | - |
| 1 | REAR LOWER BUMPER | SERVICEABLE | 930.00 | - |
| 1 | REINFORCEMENT BAR | TO REPAIR SEE LABOUR | 1,544.00 | - |
| 1 | REAR END PANEL | TO REPAIR SEE LABOUR | 882.00 | - |
| 1 | REAR END PANEL GARNISH | SERVICEABLE | 566.00 | - |
| 2 | REAR EXHAUST CHROME TIP | SERVICEABLE | 552.00 | - |
| 1 | REAR BUMPER TOW COVER | SERVICEABLE | 97.00 | - |
| 2 | REAR BUMPER REVERSE SENSOR | SERVICEABLE | 696.00 | - |
| 2 | REAR BUMPER LOWER REVERSE SENSOR | SERVICEABLE | 696.00 | - |
| 1 | REAR BOOT | TO REPAIR SEE LABOUR | 2,659.00 | - |
| 1 | REAR BOOT LOGO "VOLVO" | NOT NECESSARY | 143.00 | - |
| 1 | REAR BOOT "S60" | NOT NECESSARY | 139.00 | - |
| 1 | REAR BOOT "T5" | NOT NECESSARY | 127.00 | - |
| 1 | REAR BOOT LOCK | TO REPAIR SEE LABOUR | 599.00 | - |
| | LESS 10% DISCOUNT | | -1,161.20 | -178.00 |
| | | | 10,450.80 | 1,602.00 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | SET REAR BUMPER CLIPS (SN) | NECESSARY | 40.00 | 40.00 |
| 1 | SET REAR END PANEL GARNISH CLIPS (SN) | NOT NECESSARY | 40.00 | - |
| 1 | SET REAR BUMPER SEAL (SN) | NOT NECESSARY | 60.00 | - |
| 1 | SET REAR INNER COMPARTMENT CLIPS (SN) | NOT NECESSARY | 80.00 | - |
| | | | 220.00 | 40.00 |
| <u>LABOUR</u> | | | | |
| | SPRAY PAINTING ON ALL AFFECTED AREA. | | 800.00 | 220.00 |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---|---------------|---------------------------|-------------------|
| | LABOUR REMOVE/REFIT ACCIDENT DAMAGES PARTS TO STRAIGHTEN UP,JACK OUT,CUT/WELD AND REALIGN ACCIDENT AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF REINFORCEMENT BAR,REAR END PANEL,REAR BOOT AND REAR BOOT LOCK. | | 800.00 | 200.00 |
| | CHECK WIRING SYSTEM & LIGHT. | NOT NECESSARY | 100.00 | - |
| | ANTI RUH TREATMENT. | NOT NECESSARY | 120.00 | - |
| | TO REMOVE/REFIX/REPLACE REVERSE SENSOR. | | 180.00 | 50.00 |
| | TO REMOVE/REFIX/REFIX REAR INNER COMPARTMENT TO FACILITATE REPAIR. | NOT NECESSARY | 180.00 | - |
| | COMPUTER DIAGNOSTIC AFTER REPAIR. | NOT NECESSARY | 350.00 | - |
| | | | 2,530.00 | 470.00 |
| GRAND TOTAL | | | 13,200.80 | 2,112.00 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 1,700.00 |

Report Ref No. CS/AGI21005197/Ktf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.