

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21005200/NVF3E2

Date: 28/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900084027
Claimant Vehicle No :	SBS8609T	Insured Vehicle No :	SDV6485G
Date of Loss:	24/04/2021	Nature of Claim:	TP
		Claim No:	4452612443SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS8609T	Engine No:	6406447
Make & Model:	SCANIA KUB4X2 9.3L A/T ABS TURBO, 9.3 D (A)	Chassis No:	YS2K4X20001862944
Reg. Date:	30/04/2009 (Man. Year: 2008)	Odometer:	1016227 km
Colour:	Multi-colour		
Engine Capacity:	9290 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	950.00	950.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	1,100.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,050.00	2,050.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	143.50	143.50	0.00	0.00
Nett Amount (S\$)	2,193.50	2,193.50	0.00	0.00

INSPECTION

Date of Assignment:	27/04/2021		
Date Inspected:	28/04/2021	Inspected At:	Sbs Transit Ltd (Bedok) (HQ) 1470 BEDOK NORTH AVE 4 Singapore 489946
Estimated Period of Repair:	3.0 days		

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*VERTICAL PILLAR @ KL+KR;SIDE FRAME	Bent	228.00 F	*228.00 F
2	1		*SIDE PANEL 2.HL~JL.2.5MM ALUM	Bent	110.00 F	*110.00 F
3	1		*RADIATOR GRILL JL~KL;SIDE PANEL ASSY	Dented	612.00 F	*612.00 F
F=Franchise part.						
Total Parts (S\$)					950.00	950.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CONTRACTOR LABOUR	New	1,100.00	1,100.00
Gross Labour Cost (\$\$)			1,100.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >