

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

Tion 1	/SMR21005202/Euf3e2 5/2021	
20101	5/2021	
	0/2021	
Code: SMR	₹	
1. Policy Particulars :- (THIRD PARTY CLAIM)		
Insured Veh. SMB 1628T Veh. Inspected PC 1	1655Z	
Policy No. Coverage (\$) 0.00		
Claim No. BUS/04/21/5005 Excess (\$) 0.00		
Assign From HUA YEN Assign Date 27/0	4/2021	
2. Vehicle Particulars & Condition		
Make & Model GOLDEN DRAGON c.c 6693 XML6957J14	3	
Engine No. HIDDEN Year of Reg. 2012	2	
Chassis No. LL3BECDH3BA013097 Colour MUL	TI COLOUR	
Odometer 452077 KM Steering IN C	RDER	
Brakes IN ORDER Modification STA	NDARD ALLOY RIM	
General FAIR		
3. Conditions of Tyres		
Size Make Bala	ance	
R/H Front Tyre 275/70 R22.5 WEST LAKE 4 mr	n	
L/H Front Tyre 275/70 R22.5 WEST LAKE 4 mr	n	
R/H Rear Tyre 275/70 R22.5 (D) WEST LAKE 4/4 r	nm	
L/H Rear Tyre 275/70 R22.5 (D) WEST LAKE 4/4 r	nm	
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.		
5. General Information		
Accident Date 01/04/2021 Inspect Date / Time 28/04	4/2021(11:30 AM)	
Survey held at STS TRANSPORT MANAGEMENT PTE LTD		
15 PIONEER SECTOR 2 SINGAPORE 628376	15 PIONEER SECTOR 2 SINGAPORE 628376	
5a. Remarks		
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$400-\$500		
5b. Estimate Days of Repair		
ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Da	ays	

Report Ref No. CS3/SMR21005202/Euf3e2

Inspected By

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser