

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 8405X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	MTG CRACKED	1,600.71	1,600.71
1	REAR BUMPER RH SIDE RETAINER (CONSISTENT)	DISTORTED	289.70	289.70
1	REAR BUMPER RH '508' EMBLEM (CONSISTENT)	NECESSARY	133.96	133.96
1	RH TAILLAMP (CONSISTENT)	CUT	1,307.09	1,307.09
1	REAR RH FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	2,499.79	-
1	REAR RH FENDER UNDER SHIELD (CONSISTENT)	SERVICEABLE	288.96	-
1	SET REAR FENDER UNER SHIELD CLIPS (CONSISTENT)	NOT NECESSARY	40.00	-
1	REAR RH SPORTS RIMS (CONSISTENT)	DENTED	1,890.71	1,890.71
1	REAR RH LOWER ARM (CONSISTENT)	DISTORTED	700.78	700.78
1	REAR RH TRAILING ARM (CONSISTENT)	DISTORTED	500.99	500.99
1	REAR RH SHOCK ABSORBER (CONSISTENT)	SERVICEABLE	600.80	-
1	REAR RH KNUCKLE ARM (CONSISTENT)	BENT	800.87	800.87
1	REAR RH WHEEL HUB AND BEARING (CONSISTENT)	BENT	688.96	688.96
	LESS 10% DISCOUNT		-1,134.33	-791.38
			10,208.99	7,122.39
	<u>LABOUR</u>			
	LABOUR CHARGES FOR REMOVE /REFIT ,PANEL BEATING AND REPLACE ACCIDENT DAMAGES.INCLUSIVE OF THE REPAIR OF REAR RH FENDER .		1,100.00	700.00
	TO PUTTY AND SPRAY PAINTING CHARGES.		800.00	600.00
	TO CHECK WIRING AND LIGHTINGS.		40.00	20.00
	TO REMOVE,REFIX ROOF LINING ,REAR CUSHION SEATS & REAR UPHOLSTERY .		180.00	60.00
	TO REMOVE,REFIX REAR RH UNDER CARRIAGES.		250.00	160.00
	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST.		80.00	60.00
	TO SUPPLY AND APPLY ANTI RUST TREATMENT.	NOT NECESSARY	60.00	-
			2,510.00	1,600.00
	GRAND TOTAL		12,718.99	8,722.39

Report Ref No. CC4/ASM21005203/Kpa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		6,950.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM21005203/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser