

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005206/KPS3Q2
Date: 29/09/2021**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SKQ4446B

Date of Loss: 24/04/2021

Policy No:

Insured Vehicle No :

SMX2883A

Nature of Claim:

TP

Claim No:

7035535279SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKQ4446B**

Make & Model: AUDI A3, 1.4 TFSI S-TRONIC (A)

Reg. Date: 27/11/2014 (Man. Year: 2014)

Colour: White

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: CZC222551

Chassis No: WAUZZZ8V6FA065100

Odometer: 101605 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Front Left Side: Bridgestone 8 mm

Front Right Side: Bridgestone 8 mm

Rear Tyre Size:

205/55 R16

Rear Left Side:

Bridgestone 8 mm

Rear Right Side:

Bridgestone 8 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	547.19	547.19	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	500.00	50.00	450.00	90.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,047.19	597.19	450.00	42.97
+ GST 7.00/7.00% (S\$)	73.30	41.80	31.50	42.97

Nett Amount (S\$)	1,120.49	638.99	481.50	42.97
		<hr/>		
+ Loss of Use (1.0 x S\$60.00/day) (S\$)		60.00		
+ Doc/Search Fee (S\$)		2.00		
		<hr/>		
Nett Liability (S\$)		700.99		
		<hr/>		

INSPECTION

Date of Assignment: 27/04/2021

Date Inspected: 28/04/2021

Estimated Period of Repair: 0.5 days

Inspected At:

Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
 Singapore 568047

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Dented	475.45 FL	*475.45 FL
2	1		*RADIATOR GRILLE EMBLEM	Necessary	93.65 FL	*93.65 FL
3	1		*NUMBER PLATE	Dented	35.00 FS	*35.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (S\$)	604.10
					- List Item Discount on L Items 10.00/10.00% (S\$)	56.91
					Total Parts (S\$)	547.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD TO KNOCK & REPAIR FRONT BUMPER INNER PANEL AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	200.00	50.00
2	TO SPRAY FRONT BUMPER	New	300.00	0.00
Gross Labour Cost (\$\$)			500.00	50.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >