

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005207/KRS3Q2
Date: 16/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800104119
Claimant Vehicle No :	SKK1210R	Insured Vehicle No :	SFZ7921M
Date of Loss:	23/04/2021	Nature of Claim:	TP
		Claim No:	9085167904SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK1210R		
Make & Model:	HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A)	Engine No:	G4FGCU641763
Reg. Date:	12/06/2013 (Man. Year: 2012)	Chassis No:	KMHDH41CMDU649638
Colour:	Metallic Black	Odometer:	108462 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 2 mm	Rear Left Side:	Nexen 3 mm
Front Right Side:	Nexen 2 mm	Rear Right Side:	Nexen 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,536.32	1,752.96	2,783.36	61.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,930.00	1,960.00	970.00	33.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,466.32	3,712.96	3,753.36	50.27
Approved Total (Overridden) (S\$)		3,000.00		

(S\$)	7,466.32	3,000.00	4,466.32	59.82
+ GST 7.00/7.00% (S\$)	522.64	210.00	312.64	59.82
Nett Amount (S\$)	7,988.96	3,210.00	4,778.96	59.82
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
(S\$)		3,570.00		
Liabe Amount (70.00%) (S\$)		2,499.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,506.45		
Global Sum Settlement (S\$)		2,500.00		

INSPECTION

Date of Assignment: 27/04/2021

Date Inspected: 28/04/2021

Inspected At: Wei Lee Motor Works (HQ)
BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32
Singapore 575644

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Bent	547.30 FL	*466.00 FL
2	1		*FRONT FENDER COWLING	Serviceable	114.10 FL	*- FL
3	1		*COWLING CLIP	Not Necessary	50.00 FL	*- FL
4	1		*FRONT BUMPER	Serviceable	498.90 FL	*- FL
5	1		*BUMPER RETAINER ,LH	Serviceable	42.00 FL	*- FL
6	1		*FRONT DOOR ,LH	Dented / Warped	1,831.10 FL	*1,405.20 FL
7	1		*REAR DOOR,LH	Repair	1,775.20 FL	*- FL
8	1		*REAR BUMPER	Repair	491.80 FL	*- FL
9	1		*FRONT RIM	Dented	320.00 FL	*320.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					5,670.40	2,191.20
- List Item Discount on L Items 20.00/20.00% (S\$)					1,134.08	438.24
Total Parts (S\$)					4,536.32	1,752.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE /REINSTALL REAR WINDSCREEN GLASS	New	180.00	0.00
2	TO REMOVE /TRANSFER DOOR GLASS ,POWER WINDOW MECHANISM TO NEW DOORS -F n RR	New	150.00	60.00
3	TO REMOVE DAMAGED PARTS AND ATTACHMENTS CUT N WELD DAMAGED FENDER ,REPAIR ALL DENTED AREAS REPLACE/ALIGN ALL PARTS INTO POSITION	New	1,100.00	700.00
4	TO SPRAY PAINT	New	1,500.00	1,200.00
Gross Labour Cost (S\$)			2,930.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >