

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 6527H**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER COVER	CRACKED	1,052.20	1,052.20
1	FRONT BUMPER GRILLE/RH	SERVICEABLE	187.20	-
1	FRONT RAD GRILLE MOULDING	SERVICEABLE	94.70	-
1	FRONT BUMPER BRACKET TOP/RH	SERVICEABLE	22.40	-
1	FRONT BUMPER BRACKET RH	SERVICEABLE	24.60	-
1	FRONT FENDER LH	DEFORMED	663.00	663.00
1	FRONT FENDER SHIELD/LH	DEFORMED	174.90	174.90
1	HEAD LAMP ASSY LH	SCRATCHED	1,800.00	1,800.00
1	HEAD LAMP SUPPORT PANEL	DEFORMED	907.40	907.40
1	FRONT WHEEL CAP LH	SCRATCHED	217.20	217.20
10	BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	WIPER WASHER TANK	SERVICEABLE	61.90	-
	LESS 20% DISCOUNT		-1,045.50	-967.34
			4,182.00	3,869.36
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		600.00	560.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	REMOVE/REFIX AIR CON & CHARGE IN GAS.	NOT NECESSARY	120.00	-
	TUFF KOTE.		80.00	40.00
	CHECK LIGHTING.		60.00	30.00
			1,460.00	1,130.00
	<b>GRAND TOTAL</b>		<b>5,642.00</b>	<b>4,999.36</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>4,000.00</b>

Report Ref No. NS/INC21005209/Nqce2


**MUHAMMAD NAZRIL BIN ABDULLAH**

Automotive Assessor


**K.K.LAU CPT(RET)**
**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**
**REGD Auto Consultant-SAE, Licensed Appraiser**
**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.