

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



NTUC INCOME INSURANCE CO-OPERATIVE LTD				Ref: NS/INC21005210/Nuce2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	05-05-2021 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SDV 6898Z	1	nspected	SHC 561L	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1129927-001	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	26/04/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2019	
	Chassis No.	KMHC851CVKU141351	Colou	r	YELLOW	
	Odometer	245446	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	LAKE	5 mm	
	L/H Front Tyre	195/65 R15	WEST	LAKE	5 mm	
	R/H Rear Tyre	195/65 R15	DAVAN	ITI	4 mm	
	L/H Rear Tyre	195/65 R15	DAVAN	ITI	4 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	21/04/2021	Inspec	tion Date	26/04/2021	
	Survey held at					
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					