

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/GRB21005216/R1BS3Q2
Date: 16/08/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SFQ133P	Insured Vehicle No :	SLQ8343B
Date of Loss:	25/04/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001807

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFQ133P		
Make & Model:	MERCEDES-BENZ B180, 1.6 STYLE (R16 LED) (A)	Engine No:	27091031043834
Reg. Date:	19/12/2016 (Man. Year: 2016)	Chassis No:	WDD2462422J414556
Colour:	Black	Odometer:	83162 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,214.02	13,078.83	1,135.19	7.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,780.00	10,360.00	2,420.00	18.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,994.02	23,438.83	3,555.19	13.17
+ GST 7.00/7.00% (S\$)	1,889.58	1,640.72	248.86	13.17

Nett Amount (S\$)	28,883.60	25,079.55	3,804.05	13.17
+ Car Rental (14.0 x S\$107.00/day) (S\$)		1,498.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		26,585.00		

INSPECTION

Date of Assignment:	27/04/2021		
Date Inspected:	27/04/2021	Inspected At:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378
Estimated Period of Repair:	12.0 days		

Adjuster: MOHD RASUL**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jul 2021)
Parts:	144	MERCEDES-BENZ B180 1.6 STYLE (R16 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFQ133P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RIGHT 3/4 GLASS SOLAR FILM	Necessary	100.00 FS	*100.00 FS
2	1		*REAR RIGHT RIM	Necessary	60.00 FS	*60.00 FS
3	1		*REAR BUMPER	Cracked	1,544.63 FS	*1,544.63 FS
4	1		*REAR BUMPER TOP PLATE	Serviceable	272.36 FS	*- FS
5	1		*RH/R BUMPER SIDE BRACKET	Necessary	12.82 FS	*12.82 FS
6	1		*RH/R FENDER	Buckled	2,556.79 FS	*2,556.79 FS
7	1		*RH/R FENDER 3/4 GLASS	Necessary	230.78 FS	*230.78 FS
8	1		*GLAZING REPAIR KIT	Not Necessary	160.11 FS	*- FS
9	1		*RH/R FENDER 3/4 GLASS SEAL	Not Necessary	87.33 FS	*- FS
10	1		*ADHESIVE SEALANT	Necessary	776.81 FS	*776.81 FS
11	1		*RH/R DISC WHEEL	Scratched	522.92 FS	*522.92 FS
12	1		*RH/R DOOR SHELL	Bent	2,008.55 FS	*2,008.55 FS
13	1		*RH/R DOOR WEATHERSTRIP	Necessary	305.97 FS	*305.97 FS
14	1		*RH/R DOOR INSULATION	Necessary	72.38 FS	*72.38 FS
15	1		*RH/R DOOR WINDOW GUIDE RAIL	Necessary	133.48 FS	*133.48 FS
16	1		*RH/R DOOR LOCK	Serviceable	324.41 FS	*- FS
17	1		*RH/R SHOCK ABSORBER	Bent	293.39 FS	*293.39 FS
18	1		*REAR TORSION BAR	Serviceable	230.04 FS	*- FS
19	1		*REAR TORSION BAR ROD	Serviceable	60.94 FS	*- FS
20	1		*RH/R WHEEL CARRIER	Bent	1,308.47 FS	*1,308.47 FS
21	1		*RH/R WHEEL HUB	Bent	375.32 FS	*375.32 FS
22	1		*RH/R TIE ROD	Bent	58.18 FS	*58.18 FS
23	1		*RH/R RADIUS ROD	Bent	149.53 FS	*149.53 FS
24	1		*RH/R CAMBER ARM	Bent	134.26 FS	*134.26 FS
25	1		*RH/R SPRING LINK	Bent	190.69 FS	*190.69 FS
26	1		*REAR AXLE CARRIER	Bent	1,893.93 FS	*1,893.93 FS
27	2		*HEXALOBULAR BOLT	Necessary	33.86 FS	*33.86 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	2		*COMBI-SCREW	Necessary	41.96 FS	*41.96 FS
29	2		*COMBINATION BOLT	Necessary	43.36 FS	*43.36 FS
30	1		*TWO-COMPONENT ADHESIVE	Necessary	102.00 FS	*102.00 FS
31	1		*SEAM SEAL	Necessary	104.99 FS	*104.99 FS
32	9		*BLIND RIVET WITH PAN HEAD	Necessary	23.76 FS	*23.76 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	14,214.02
						13,078.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
2	REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR	New	1,440.00	960.00
3	INSPECT & CONDUCT WHEEL ALIGNMENT	New	540.00	540.00
4	REMOVE & INSTALL REAR SUSPENSION & WHEEL BASE	New	2,400.00	1,920.00
5	TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR	New	480.00	480.00
6	REMOVE & REPLACE REAR BUMPER ,REAR RIGHT FENDER ,REAR RIGHT DOOR & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH	New	4,800.00	3,840.00
7	RESPRAY REAR BUMPER ,REAR RIGHT FENDER ,REAR RIGHT DOOR & REAR END PANEL	New	2,600.00	2,100.00
8	ACCIDENT TOWING FROM 3 JALAN JELITA TO PLSC USING KING DOLLEY AND SUNDAY CHARGE	New	140.00	140.00
Gross Labour Cost (\$\$)			12,780.00	10,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >