

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMT 3622B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	BUCKLED / MTG CRACKED	1,459.00	1,150.00
2	REAR BUMPER BRACKET @\$65.00 (CONSISTENT)	TO REPAIR SEE LABOUR	130.00	-
6	REAR BUMPER CLIP @\$6.00 (CONSISTENT)	NECESSARY	36.00	36.00
1	REAR BUMPER SIDE RETAINER L/H (CONSISTENT)	DISTORTED	48.00	48.00
1	REAR BUMPER REFLECTOR L/H (CONSISTENT)	SERVICEABLE	115.00	-
1	REAR SPLASH SHIELD L/H (CONSISTENT)	CRACKED	155.00	155.00
1	REAR MUDFLAP L/H (CONSISTENT)	CUT	92.00	92.00
1	REAR SHOCK ABSORBER L/H (CONSISTENT)	SERVICEABLE	585.00	-
1	REAR WHEEL BEARING L/H (CONSISTENT)	BENT	350.00	285.00
	LESS 25% DISCOUNT		-742.50	-441.50
			2,227.50	1,324.50
	SPECIAL NETT ITEMS			
1	REAR SPORT RIM L/H (SN) (CONSISTENT)	DENTED	750.00	400.00
			750.00	400.00
	<u>LABOUR</u>			
	REMOVE & REINSTALL REAR SUSPENSION L/H.		250.00	30.00
	COMPUTER ALL WHEEL ALIGNMENT.		120.00	60.00
	SPRAY PAINT DAMAGED AREA AFFECTED .		700.00	200.00
	TO KNOCK AND STRAIGHTEN REAR L/H CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET.		600.00	200.00
			1,670.00	490.00
	GRAND TOTAL		4,647.50	2,214.50



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,750.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM21005217/Kga3q2

KONG SENG CHEONG

Licensed Appraiser