



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG			Ref: CC4/ASM21005217/Kga3q2 Date: 19/10/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4362M	Veh. Inspected	SMT 3622B	
Policy No.	P2426680	Coverage (\$)	0.00	
Claim No.	S1M038WM	Excess (\$)	0.00	
Assign From		Assign Date	27/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JTNK93BE903001974	Colour	METALLIC SILVER	
Odometer	32347 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R17	MAXXIS	8 mm	
L/H Front Tyre	215/50 R17	MAXXIS	8 mm	
R/H Rear Tyre	215/50 R17	MAXXIS	8 mm	
L/H Rear Tyre	215/50 R17	MAXXIS	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/04/2021	Inspection Date	29/04/2021	
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	