

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 357K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER ASSY	DEFORMED	458.60	458.60
1	REAR BUMPER UNDER COVER	DEFORMED	552.60	552.60
1	REAR BUMPER TOW COVER	DEFORMED	82.70	82.70
1	TAILAMP LOWER ASSY RH	CRACKED	548.40	548.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
	LESS 25% DISCOUNT		-416.08	-416.08
			1,248.22	1,248.22
<u>SPECIAL NETT ITEMS</u>				
2	REAR FENDER RH / LH ADVERTISEMENT LOGO (SN)	NECESSARY	200.00	200.00
			200.00	200.00
<u>LABOUR</u>				
	PANEL BEATING.		400.00	350.00
	SPRAY PAINT.		300.00	250.00
	REMOVE / REFIX REVERSE SENSOR.		80.00	30.00
	CHECK WIRING.		50.00	30.00
			830.00	660.00
GRAND TOTAL			2,278.22	2,108.22
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,108.22

Report Ref No. NS/INC21005223/Nqce2



MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.