

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21005234/AQCE2

**Date:** 11/08/2021

### REFERENCE

Insured/Claimant:	ANG HAO CHIEH	Policy No:	7210002868		
Date of Loss:	21/04/2021	Nature of Claim:	OD	Claim No:	2080702676SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX4205U		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZDC23822
Reg. Date:	12/01/2021 (Man. Year: 2020)	Chassis No:	WAUZZZF37M1064715
Colour:	Blue	Odometer:	5307 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$165,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,367.00	428.80	9,938.20	95.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,972.00	2,272.00	3,700.00	61.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,339.00</b>	<b>2,700.80</b>	<b>13,638.20</b>	<b>83.47</b>
<b>- Excess (S\$)</b>	400.00	400.00	0.00	0.00
<b>(S\$)</b>	15,939.00	2,300.80	13,638.20	85.56
<b>+ GST 7.00/7.00% (S\$)</b>	1,115.73	161.06	954.67	85.56
<b>Nett Amount (S\$)</b>	<b>17,054.73</b>	<b>2,461.86</b>	<b>14,592.87</b>	<b>85.56</b>

### INSPECTION

Date of Assignment:	28/04/2021		
Date Inspected:	27/04/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Repair	1,153.00 FS	*- FS
2	1	*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	59.00 FS	*- FS
3	1	*FRONT BUMPER GRILLE - CENTER	Not Necessary	217.00 FS	*- FS
4	1	*FRONT BUMPER GRILLE - RH	Not Necessary	110.00 FS	*- FS
5	1	*FRONT BUMPER CLOSING ELEMENT	Not Necessary	190.00 FS	*- FS
6	1	*FRONT BUMPER ARCH SPOILER	Not Necessary	383.00 FS	*- FS
7	1	*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	153.00 FS	*- FS
8	1	*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	39.00 FS	*- FS
9	1	*FRONT FENDER - RH	Repair	1,286.00 FS	*- FS
10	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	63.00 FS	*- FS
11	1	*FRONT FENDER BRACE - RH	Not Necessary	88.00 FS	*- FS
12	1	*FRONT FENDER BRACKET - RH	Not Necessary	32.00 FS	*- FS
13	1	*FRONT WHEEL HOUSING LINER - RH (NPA)	Not Necessary	0.00 FS	*- FS
14	1	*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	101.00 FS	*- FS
15	1	*HEADLIGHT MOUNTING - RH	Not Necessary	118.00 FS	*- FS
16	1	*HEADLIGHT - RH	Not Necessary	5,589.00 FS	*- FS
17	2	*FRONT WHEEL ARCH COVER - LH / RH	N/S Necessary / O/S Cut	536.00 FS	*428.80 FS
18	1	*SUNDRIES	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 10,367.00 428.80

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	500.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,972.00</b>	<b>2,272.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >