Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Adeline Chng Pei Wen Date: 03 Jun 2021

Preliminary Advice

Insured Vehicle No : XD6359X

TP Vehicle No : 23/04/2021 : SJQ1696C Accident Date Make : PERODUA MYVI Assignment Date : 27/04/2021

Date of Inspection : 28/04/2021 Est. Duration of Repair

Inspection At : SK AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4, #08-46 PREMIER @ KAKI BUKIT

SINGAPORE 415875

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 26,874.23 |
|-----------------------------|------|-----------|
| Revised Amount | :S\$ | 11,424.50 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 11,424.50 |
| | | |
| Lump Sum Repair | :S\$ | 9.100.00 |

Total Loss Consideration

| New for Old Value | :S\$ |
|--------------------|------|
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

| (|) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. |
|---|---|---|
| (|) | The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. |
| (|) | Other comments : |