



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG			Ref: CS/ASM21004504/Bpa3q2-1 Date: 05/11/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLQ 5592T	Veh. Inspected	GBK 4718E
	Policy No.	GA238794	Coverage (\$)	0.00
	Claim No.	S1M036FR	Excess (\$)	0.00
	Assign From		Assign Date	26/03/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2754
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	GDH2012012012559	Colour	SILVER
	Odometer	23822 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/80 R15	MICHELIN	6 mm
	L/H Front Tyre	195/80 R15	MICHELIN	6 mm
	R/H Rear Tyre	195/80 R15	DUNLOP	6 mm
	L/H Rear Tyre	195/80 R15	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/03/2021	Inspection Date	08/04/2021
	Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	