

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III21005248/APA3Q2

Date:

07/07/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: D19MFL0005549_01

Claimant Vehicle No : SMW9205S**Insured Vehicle No :** GBJ3864C

Date of Loss: 27/04/2021

Nature of Claim:

TP

Claim No:

MFL2021D0001910

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMW9205S**

Make & Model: TOYOTA ALPHARD, 2.5 (A)

Engine No: 2ARH594836

Reg. Date: 01/03/2016 (Man. Year: 2015)

Chassis No: AGH300027384

Colour: Grey

Odometer: 75799 km

Engine Capacity: 2493 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,912.47	9,399.15	2,513.32	21.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	2,070.00	1,730.00	45.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,712.47	11,469.15	4,243.32	27.01
+ GST 7.00/7.00% (S\$)	1,099.87	802.84	297.03	27.01

Nett Amount (S\$)	16,812.34	12,271.99	4,540.35	27.01
+ Car Rental (8.0 x S\$110.00/day) (S\$)		880.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		13,159.48		
Global Sum Settlement (S\$)		13,100.00		

INSPECTION

Date of Assignment: 28/04/2021

Date Inspected: 28/04/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Modern Automotive Pte Ltd (HQ)
 Blk 3023A Ubi Road 1, #01-61 & #01-58
 Singapore 408717

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jun 2021)
Parts:	M1-MPV	TOYOTA ALPHARD 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW9205S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,614.10 FL	*1,614.10 FL
2	1		*FRONT BUMPER SIDE HOLDER -LH	Damaged	131.20 FL	*131.20 FL
3	1		*FRONT BUMPER SENSOR -LH	Not Necessary	381.80 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP -LH	Not Necessary	339.50 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP COVER-LH	Deformed	272.40 FL	*272.40 FL
6	1		*FRONT BUMPER FOG LAMP COVER CHROME-LH	Cut	142.40 FL	*142.40 FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	497.20 FL	*- FL
8	1		*FRONT GRILLE ASSY	Cracked	1,124.50 FL	*1,124.50 FL
9	1		*HEAD LAMP -LH	Cracked	3,486.40 FL	*3,486.40 FL
10	1		*HEAD LAMP CONTROL UNIT-LH	Damaged	382.40 FL	*382.40 FL
11	1		*FRONT SUPPORT PANEL	Repair	889.40 FL	*- FL
12	1		*BONNET	Dented	880.60 FL	*880.60 FL
13	2		*BONNET HINGES	Not Necessary	152.20 FL	*- FL
14	1		*FRONT FENDER -LH	Distorted	789.20 FL	*789.20 FL
15	1		*FRONT FENDER BRACKET-LH	Bent	45.90 FL	*45.90 FL
16	1		*FRONT FENDER INNER SHIELD -LH	Not Necessary	281.40 FL	*- FL
17	1		*FRONT FENDER MIRROR -LH	Repair	369.60 FL	*- FL
18	1		*WIPER PANEL SIDE GARNISH -LH	Deformed	58.40 FL	*58.40 FL
19	1		*FRONT PILLAR MOULDING -LH	Cut	110.40 FL	*110.40 FL
20	1		*WIPER WASHER TANK	Deformed	154.20 FL	*154.20 FL
21	1		*FRONT WHEEL RIM -LH	Cut	1,180.00 FL	*1,180.00 FL
22	1		*FRONT SHOCK ABSORBER -LH	Bent	481.90 FL	*481.90 FL
23	1		*FRONT KNUCKLE ARM -LH	Damaged	561.60 FL	*561.60 FL
24	1		*FRONT LOWER ARM -LH	Bent	585.20 FL	*585.20 FL
25	1		*FRONT WHEEL HUB C/W BEARING -LH	Damaged	451.40 FL	*451.40 FL
26	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
27	1		*FRONT GRILLE CLIPS	Necessary	30.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
29	1		*FRONT TYRE-LH	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					15,753.30	12,512.20
- List Item Discount on L Items 25.00/25.00% (\$)					3,840.83	3,113.05
Total Parts (\$)					11,912.47	9,399.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OUT FRONT LH PORTION & RENEW ABOVE PARTS	New	1,500.00	800.00
2	TO PUTTY & SPRAY UP PAINT WORKS (FRONT)	New	1,400.00	900.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE CONDENSER & TOP UP AIRCON GAS	New	100.00	0.00
5	TO REMOVE RADIATOR & TO UP COOLANT	New	100.00	0.00
6	TO SPRAY TUFF COAT (FRONT)	New	150.00	40.00
7	TO REMOVE FRONT UNDERCARRIAGE	New	350.00	220.00
8	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (S\$)			3,800.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >