

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21005251/NVF3E2

Date: 21/10/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00071762100
Claimant Vehicle No: SLZ6190R Insured Vehicle No: SGL9604C
Date of Loss: 20/04/2021 Nature of Claim: TP Claim No: SNM21D202279/C2/TANKAHLEONG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ6190R**
Make & Model: HONDA FREED, 1.5 (A) Engine No: LEB5593119
Reg. Date: 11/05/2018 (Man. Year: 2018) Chassis No: GB71061337
Colour: Red Odometer: 189495 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: Firenza 4 mm Rear Left Side: West Lake 4 mm
Front Right Side: Firenza 4 mm Rear Right Side: West Lake 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,806.00	6,357.28	7,448.72	53.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,600.00	2,220.00	5,380.00	70.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,406.00	8,577.28	12,828.72	59.93
Approved Total (Overridden) (S\$)		6,850.00		
(S\$)	21,406.00	6,850.00	14,556.00	68.00
+ GST 7.00/7.00% (S\$)	1,498.42	479.50	1,018.92	68.00
Nett Amount (S\$)	22,904.42	7,329.50	15,574.92	68.00

INSPECTION

Date of Assignment: 28/04/2021
Date Inspected: 29/04/2021 Inspected At: 56 Loyang Way #04-04
Estimated Period of Repair: 6.0 days Repairer: AP Automotive Services Pte Ltd

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2021)
Parts:	M1-MPV	HONDA FREED 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ6190R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	981.00 FL	*800.00 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	102.00 FL	*102.00 FL
3	1		*TAILGATE WIPER MOTOR	Serviceable	365.00 FL	*- FL
4	1		*TAILGATE LOGO - HONDA	Necessary	49.00 FL	*49.00 FL
5	1		*TAILGATE EMBLEM - FREED	Necessary	54.00 FL	*54.00 FL
6	1		*TAILGATE CHROME GARNISH	Cracked	198.00 FL	*198.00 FL
7	1		*TAILGATE HANDLE OPENER	Serviceable	132.00 FL	*- FL
8	2		*TAILGATE NUMBER PLATE LAMP L+R	Not Working	120.00 FL	*80.00 FL
9	2		*TAILGATE LAMP L+R	Cracked	790.00 FL	*790.00 FL
10	1		*TAILGATE LOCK	Deformed	135.00 FL	*135.00 FL
11	1		*TAILGATE LOCK CATCH	Deformed	91.20 FL	*91.20 FL
12	1		*TAILGATE INNER TRIM	Cracked	231.00 FL	*231.00 FL
13	1		*TAILGATE HINGE L+R	N/S Serviceable / O/S Bent	191.40 FL	*70.00 FL
14	2		*TAILGATE DAMPER L+R	Not Working	304.00 FL	*160.00 FL
15	1		*TAILGATE INNER HANDLE	Deformed	41.00 FL	*41.00 FL
16	1		*TAILGATE WEATHERSTRIP	Deformed	125.00 FL	*125.00 FL
17	2		*TAIL LAMP L+R	Cracked	1,180.00 FL	*900.00 FL
18	2		*TAIL LAMP PANEL L+R	Serviceable	390.00 FL	*- FL
19	1		*REAR BUMPER	Cracked	682.00 FL	*682.00 FL
20	1		*REAR BUMPER TOW COVER	Serviceable	40.00 FL	*- FL
21	2		*REAR BUMPER REFLECTOR L+R	Serviceable	160.00 FL	*- FL
22	2		*REAR BUMPER REVERSE SENSOR	Deformed	470.00 FL	*360.00 FL
23	2		*REAR BUMPER RETAINER L+R	Cracked	158.90 FL	*158.90 FL
24	2		*REAR FENDER L+R	Serviceable	2,432.00 FL	*- FL
25	2		*REAR FENDER WINDOW MOULDING L+R	Not Necessary	302.00 FL	*- FL
26	2		*REAR FENDER INNER TRIM L+R	Cracked	584.00 FL	*400.00 FL
27	2		*REAR FENDER COWLING L+R	Serviceable	180.00 FL	*- FL
28	1		*END PANEL	Dented	362.00 FL	*362.00 FL
29	1		*END PANEL TOP GARNISH	Cracked	97.00 FL	*97.00 FL
30	1		*REAR SMART LOCK ANTENNA	Cracked	98.00 FL	*98.00 FL
31	1		*FLOOR PANEL	Dented	921.00 FL	*700.00 FL
32	1		*FLOOR PANEL TOP BOARD	Deformed	570.00 FL	*350.00 FL
33	1		*EXHAUST PIPE	Repair	779.00 FL	*- FL
34	2		*EXHAUST MOUNTING	Serviceable	150.00 FL	*- FL
35	1		*EXHAUST HEAT SHIELD (NPA)	Serviceable	0.00 FL	*- FL
36	1		*TAILGATE WINDSCREEN SEALANT	Necessary	150.00 FS	*60.00 FS
37	1		*TAILGATE INNER TRIM CLIPS	Necessary	150.00 FS	*50.00 FS
38	1		*REAR NUMBER PLATE	Serviceable	120.00 FS	*- FS
39	1		*REVERSE CAMERA	Not Working	850.00 FS	*350.00 FS
40	1		*TAIL LAMP CLIPS	Necessary	20.00 FS	*20.00 FS
41	2		*TAIL LAMP PANEL SEALANT	Not Necessary	200.00 FS	*- FS
42	2		*REAR FENDER SEALANT L+R	Not Necessary	400.00 FS	*- FS
43	2		*REAR FENDER COWLING CLIPS	Not Necessary	200.00 FS	*- FS
44	2		*REAR FENDER WINDOW SEALANT	Not Necessary	240.00 FS	*- FS
45	1		*END PANEL SEALANT	Necessary	250.00 FS	*80.00 FS
46	1		*END PANEL TOP GARNISH CLIPS	Necessary	100.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FLOOR PANEL SEALANT	Necessary	300.00 FS	*80.00 FS
48	1		*TAILGATE EMBLEM - HYBRID	Necessary	67.00 FL	*50.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					16,512.50	7,774.10
- List Item Discount on L Items 20.00/20.00% (S\$)					2,706.50	1,416.82
Total Parts (S\$)					13,806.00	6,357.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,200.00	1,000.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,600.00	800.00
3	TO RNR REAR WINDSCREEN	New	400.00	120.00
4	TO RNR REAR FENDER WINDOW	New	300.00	0.00
5	TO RNR REAR EXHAUST	New	250.00	0.00
6	TO CHECK WIRING AND TAIL LAMP FUNCTION	New	150.00	30.00
7	TO CHECK WIRING AND TAILGATE LAMP FUNCTION	New	150.00	30.00
8	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	80.00
9	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	0.00
10	TO RNR UNDERCARRIAGE	New	250.00	0.00
11	TO CHECK WATER LEAK	New	100.00	0.00
12	TO RNR FUEL TANK	New	250.00	0.00
13	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
14	TO RNR REAR TAILGATE MECHANISM	New	350.00	50.00
15	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
16	TO PERFORM RUST PROOFING	New	200.00	80.00
Gross Labour Cost (\$\$)			7,600.00	2,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >