

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005253/APA3Q2
Date: 12/07/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100340610
Claimant Vehicle No :	SMD2845R	Insured Vehicle No :	GBC6618P
Date of Loss:	26/04/2021	Nature of Claim:	TP
		Claim No:	1491545797SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD2845R	Engine No:	R18A1800961
Make & Model:	HONDA STREAM, 1.8 (A)	Chassis No:	RN61090970
Reg. Date:	16/02/2009 (Man. Year: 2008)	Odometer:	190173 km
Colour:	White		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,843.28	2,526.00	6,317.28	71.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,145.00	1,770.00	2,375.00	57.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,988.28	4,296.00	8,692.28	66.92
Approved Total (Overridden) (S\$)		3,400.00		

(S\$)	12,988.28	3,400.00	9,588.28	73.82
+ GST 7.00/7.00% (S\$)	909.18	238.00	671.18	73.82
Nett Amount (S\$)	13,897.46	3,638.00	10,259.46	73.82
+ Car Rental (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,240.00		
Global Sum Settlement (S\$)		4,240.00		

INSPECTION

Date of Assignment: 28/04/2021

Date Inspected: 28/04/2021

Inspected At:

SK Automobile Pte Ltd (HQ)
 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre
 Singapore 415933

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	903.30 FL	*903.30 FL
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	65.40 FL	*65.40 FL
3	1		*REAR TAILGATE OUTER GARNISH	Cracked	162.40 FL	*162.40 FL
4	1		*REAR TAILGATE LOGO EMBLEM	Not Necessary	31.90 FL	*- FL
5	1		*REAR TAILGATE STREAM EMBLEM	Necessary	31.60 FL	*31.60 FL
6	1		*REAR TAILGATE OUTER LOCK HANDLE	Not Necessary	68.20 FL	*- FL
7	2		*REAR TAILGATE NUMBER PLATE LAMP LH/RH	Not Necessary	65.60 FL	*- FL
8	2		*REAR TAILGATE HINGE LH/RH	Not Necessary	92.40 FL	*- FL
9	2		*REAR TAILGATE DAMPER LH/RH	Not Necessary	252.40 FL	*- FL
10	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	141.20 FL	*141.20 FL
11	1		*REAR TAILGATE INNER HANDLE	Not Necessary	25.60 FL	*- FL
12	2		*REAR TAILGATE RUBBER GUIDE STOPPER LH/RH	Not Necessary	19.00 FL	*- FL
13	1		*REAR TAILGATE MECHANISM LOCK	Damaged	109.40 FL	*109.40 FL
14	1		*REAR TAILGATE WEATHERSTRIP	Cut	121.60 FL	*121.60 FL
15	1		*REAR BUMPER	Distorted	588.20 FL	*588.20 FL
16	1		*REAR BUMPER TOW HOOK COVER	Deformed	23.50 FL	*23.50 FL
17	2		*REAR BUMPER SIDE RETAINER LH/RH	Necessary	58.80 FL	*58.80 FL
18	2		*REAR BUMPER LOWER BRACKET LH/RH	Bent	41.20 FL	*41.20 FL
19	2		*REAR TAILLAMP LH/RH	Not Necessary	704.80 FL	*- FL
20	2		*REAR TAILLAMP INNER PANEL LH/RH	Not Necessary	291.80 FL	*- FL
21	2		*REAR TAILLAMP LOWER BRACKET LH/RH	Not Necessary	41.20 FL	*- FL
22	1		*REAR END PANEL	Dented	306.70 FL	*306.70 FL
23	1		*REAR END PANEL INNER TOP GARNISH	Cracked	116.70 FL	*116.70 FL
24	2		*REAR FENDER INNER TRIM BOARD LH/RH	Not Necessary	394.40 FL	*- FL
25	2		*REAR FENDER INNER AIR VENT LH/RH	Not Necessary	51.40 FL	*- FL
26	1		*REAR FLOOR PANEL	Repair	1,062.70 FL	*- FL
27	1		*REAR FLOOR PANEL INNER TOP GARNISH	Not Necessary	130.20 FL	*- FL
28	2		*REAR FLOOR PANEL INNER TOP UPHOLSTERY BOARD LH/RH	Not Necessary	597.20 FL	*- FL
29	2		*REAR FLOOR SIDE PANEL LH/RH	Repair	286.40 FL	*- FL
30	1		*SPARE TYRE BRACKET	Not Necessary	121.60 FL	*- FL
31	1		*SET SPARE TYRE SCREW LOCK	Not Necessary	39.20 FL	*- FL
32	1		*REAR EXHAUST SILENCER BOX	Not Necessary	709.50 FL	*- FL
33	2		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	48.60 FL	*- FL
34	1		*SET REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER	Necessary	100.00 FS	*60.00 FS
35	1		*SET REAR TAILGATE WINDSCREEN CAMERA RECORDER	Not Necessary	680.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
37	1		*SET REAR TAILGATE REVERSE CAMERA	Not Necessary	480.00 FS	*- FS
38	1		*SET REAR TAILGATE NUMBER PLATE WITH CASING	Not Necessary	65.00 FS	*- FS
39	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
40	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
41	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
42	2		*REAR TAILLAMP CLIPS SET LH/RH	Not Necessary	100.00 FS	*- FS
43	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
44	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	60.00 FS	*10.00 FS
45	2		*REAR FENDER INNER TRIM BOARD CLIP SET LH/RH	Not Necessary	120.00 FS	*- FS
46	1		*REAR FLOOR PANEL SEALANT	Not Necessary	120.00 FS	*- FS
47	1		*REAR FLOOR PANEL INSULATOR MAT	Not Necessary	350.00 FS	*- FS
48	1		*SET REAR FLOOR PANEL INNER TOP GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
49	1		*REAR EXHAUST GASKET	Not Necessary	25.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,384.10	3,060.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,540.82	534.00
Total Parts (\$)	8,843.28	2,526.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	1,800.00	600.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	1,400.00	800.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	125.00	60.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	30.00
5	TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM	New	150.00	120.00
6	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	80.00	50.00
7	TO DISMANTLE & REPLACED REAR TAILGATE REVERSE CAMERA WITH SETTING	New	150.00	50.00
8	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	280.00	60.00
9	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	0.00
Gross Labour Cost (\$\$)			4,145.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >