

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21005261/AVF3S2
Date: 30/05/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00022872100
Claimant Vehicle No :	SLJ1898A	Insured Vehicle No :	SMD8924G
Date of Loss:	26/04/2021	Nature of Claim:	TP
			Claim No: SNM21D202446/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ1898A		
Make & Model:	NISSAN SYLPHY, 1.5 (A)	Engine No:	HR16932831C
Reg. Date:	25/10/2018 (Man. Year: 2018)	Chassis No:	MNTBBAB17Z0033197
Colour:	Red	Odometer:	55029 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,315.41	2,629.83	5,685.58	68.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,780.00	1,460.00	3,320.00	69.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,095.41	4,089.83	9,005.58	68.77
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	13,095.41	3,200.00	9,895.41	75.56

INSPECTION

Date of Assignment:	29/04/2021		
Date Inspected:	29/04/2021	Inspected At:	Xin Hua Workshop Pte Ltd 8 KAKI BUKIT AVE 4 #04-07 Singapore 415875
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2022)
Parts:	143	NISSAN SYLPHY 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ1898A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	845.60 FN	*- FN
2	1		*BOOTLID SMART ANTENNA	Cracked	252.80 FN	*128.00 FN
3	1		*BOOTLID OUTER CHROME GARNISH	Not Necessary	298.30 FN	*- FN
4	2		*BOOTLID REFLECTORS	Not Necessary	571.80 FN	*- FN
5	2		*BOOTLID NUMBER PLATE LAMPS	Not Necessary	176.40 FN	*- FN
6	1		*BOOTLID EMBLEM SYLPHY	Necessary	97.60 FN	*97.60 FN
7	1		*BOOTLID LOGO	Necessary	98.50 FN	*98.50 FN
8	1		*BOOTLID INNER TRIM	Not Necessary	325.80 FN	*- FN
9	1		*BOOTLID INNER LOCK	Damaged	178.50 FN	*71.00 FN
10	1		*BOOTLID LOWER LATCH	Not Necessary	68.70 FN	*- FN
11	1		*BOOTLID WEATHERSTRIP	Cut	185.60 FN	*93.00 FN
12	2		*BOOTLID HINGE	Not Necessary	251.60 FN	*- FN
13	1		*REAR BUMPER	Deformed	653.70 FN	*653.70 FN
14	2		*REAR BUMPER REFLECTORS	Not Necessary	171.20 FN	*- FN
15	2		*REAR BUMPER RETAINERS	Necessary	220.40 FN	*70.00 FN
16	1		*REAR BUMPER SPONGE	Cracked	198.50 FN	*78.00 FN
17	2		*REAR BUMPER SUPPORT BRACKETS	Not Necessary	271.80 FN	*- FN
18	2		*TAILLAMPS	Cracked	796.40 FN	*796.40 FN
19	1		*END PANEL	Dented	438.50 FN	*438.50 FN
20	1		*END PANEL TOP GARNISH	Deformed	189.30 FN	*64.00 FN
21	1		*REVERSE SENSOR WIRE HARDNESS	Not Necessary	385.90 FN	*- FN
22	2		*REAR FENDER INNER COWLING	Not Necessary	316.40 FN	*- FN
23	2		*REAR FENDER INNER TRIM	Not Necessary	579.00 FN	*- FN
24	1		*REAR TOOL BOX SPONGE	Not Necessary	223.90 FN	*- FN
25	1		*REAR SPARE TYRE TOP BOARD	Not Necessary	398.70 FN	*- FN
26	1		*SET REAR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
27	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
28	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
29	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
30	1		*SET REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
31	2		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	60.00 FS	*- FS
32	2		*SET REAR FENDER INNER TRIMS	Not Necessary	60.00 FS	*- FS
33	1		*SET REAR BOOT INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
34	2		*END PANEL INSULATOR SEAL	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	9,134.90	2,888.70
- Nett Item Discount on N Items 10.00/10.00% (S\$)	819.49	258.87
Total Parts (S\$)	8,315.41	2,629.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGN ALL PARTS.	New	1,800.00	600.00
2	TO RESPRAY AFFECTED PARTS.	New	1,800.00	600.00
3	TO TUFF COAT AFFECTED AREA.	New	200.00	60.00
4	TO REMOVE / REFIT INTERIOR UPHOLSTERY.	New	180.00	60.00
5	TO APPLY SEALANT AND UNDERCOATING TO THE AFFECTED AREAS.	New	200.00	60.00
6	TO REMOVE / REFIT WIRING CHECKS ON REAR TAILLAMPS.	New	150.00	30.00
7	TO REMOVE / REPLACE REAR SILENCER BOX.	New	150.00	0.00
8	TO REMOVE / REPLACE REVERSE SENSOR AND DISTANCE SETTING.	New	150.00	50.00
9	TO REMOVE AND REPLACE BOOTLID MECHANISM.	New	150.00	0.00
Gross Labour Cost (S\$)			4,780.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >