



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 9498M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER COVER	TO REPAIR SEE LABOUR	418.30	-
10	FRT BUMPER CLIPS @\$2.20	NOT NECESSARY	22.00	-
1	FRT BUMPER BRACKET RH	SERVICEABLE	28.00	-
1	FRT FENDER RH	DENTED	588.80	588.80
1	FRT FENDER SHIELD RH	SERVICEABLE	164.70	-
1	FRT FENDER EMBLEM "BLUE DRIVE" RH	NECESSARY	26.60	26.60
1	GARNISH ASSY DELTA	SERVICEABLE	42.80	-
1	FRT DOOR RH	TO REPAIR SEE LABOUR	1,797.20	-
1	ROCKER PANEL OUTER GARNISH RH	DEFORMED	290.00	290.00
1	FRT DOOR MIRROR ASSY RH	TO REPAIR SEE LABOUR	1,391.70	-
	LESS 20% DISCOUNT		-954.02	-181.08
			3,816.08	724.32
	<u>SPECIAL NETT ITEMS</u>			
1	FRT DOOR COMFORT LOGO RH (SN)	NECESSARY	75.00	75.00
			75.00	75.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT BUMPER COVER,FRT DOOR RH AND FRT DOOR MIRROR ASSY RH.		800.00	700.00
	SPRAY PAINTING CHARGE.		1,200.00	800.00
	TUFF KOTE.		50.00	40.00
	TRANSFER OF DOOR.	NOT NECESSARY	120.00	-
			2,170.00	1,540.00
	GRAND TOTAL		6,061.08	2,339.32

RECOMMENDED COST OF REPAIRS (CONFIRMED)			2,339.32
--	--	--	-----------------

Report Ref No. NS/INC21005262/Nvcn2



MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.