ASS. REC. BY: NAO_	INC LOKE PAP
141)	
From: Date: Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No: at Workshop m/s of Insured: Policy No. Claims No. Sum Insured: Excess: (Client's Record)	Veh No: SHA 9498M Yr Regn: 9 OCTI 2019 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxib Prime Mover / Truck / Trailer or Make: HYWWDAI 10N (Q G) Colour YELLOW A/C: Insured Std / NI / NA Sp.Reading T/Radio Insured Std / NI / NA Eng/No: C/No: CM 14 C 85 (CV L U 1985 18 Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or Modi: Nil / \$/Rim / STD A/Rim or
Make of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: GIA / PR Seen: Consistent?: Yes or No Est. Repairs: Adays Res.: Yes or No Lum Sum: M/S O/S LHS RES LHS RES Vehicle: IN / OUT Date / Time Action / Instruction	Tyre Size: F: 195/65 RIS R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / 7 tyrl Dravds TOYO / YOKO or Front Rear R/Bal. mm R/Bal. mm L/Bal. mm D.O.A. 27/4/2021 Survey held at Des. of Damages: Frt / Rear / O/S N/S / U/C / Rooftop or FRONT OFF SIXE MEALSION. The U/C / Chassis frame / Body Structure affected due to collision.
Date/Time, File Pass to? Prell. Report	Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportation: S+RS_SI Photos Interview (\$) Tech. Invs (\$) Weekend (\$) TOTAL