

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21005263/KTF3N2**Date:** 10/09/2021REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001448791

Claimant Vehicle No : SGZ2233L**Insured Vehicle No :** GBD2471R

Date of Loss: 17/04/2021

Nature of Claim: TP Claim No: 256272

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGZ2233L**

Make & Model: SUBARU FORESTER, 2.0 XT CVT AWD SR (A)

Engine No: FA20K964597

Reg. Date: 22/10/2015 (Man. Year: 2015)

Chassis No: JF1SJGK85FG058325

Colour: Metallic Dark Grey

Odometer: 121730 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R18

Rear Tyre Size: 225/55R18

Front Left Side: Michelin 8 mm

Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 8 mm

Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,975.56	8,490.92	484.64	5.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	2,970.00	380.00	11.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,325.56	11,460.92	864.64	7.02
Approved Total (Overridden) (\$\$)		8,900.00		
(\$\$)	12,325.56	8,900.00	3,425.56	27.79
+ GST 7.00/7.00% (\$\$)	862.79	623.00	239.79	27.79
Nett Amount (\$\$)	13,188.35	9,523.00	3,665.35	27.79

INSPECTION

Date of Assignment: 28/04/2021

Date Inspected: 29/04/2021 Inspected At:

10 ANG MO KIO IND PARK 2A
#01-04 ANG MO KIO AUTOPOINT
SINGAPORE 568047
REPAIRER: CHENG HOE MOTOR PTE LTD

Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Sep 2021)

Parts: M1-SUV SUBARU FORESTER 2.0 XT CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGZ2233L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent/Torn	660.30 FL	*660.30 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	320.30 FL	*320.30 FL
3	2		*REAR BUMPER SIDE RETAINER	Distorted	32.20 FL	*32.20 FL
4	5		*REAR BUMPER CLIP	Necessary	19.00 FL	*19.00 FL
5	2		*REAR BUMPER INNER SHIELD	Distorted/Cracked	128.60 FL	*128.60 FL
6	1		*REAR BUMPER RH REFLECTOR	Missing	24.80 FL	*24.80 FL
7	2		*TAILLAMP	O/s Cracked/N/s Cut	874.40 FL	*874.40 FL
8	1		*RH TAILLAMP INNER TOP GARNISH	Missing	67.00 FL	*67.00 FL
9	1		*TAILLAMP LOWER RETAINER	O/s Cracked	40.60 FL	*20.30 FL
10	1		*REAR TAILGATE	Bent	1,072.80 FL	*1,072.80 FL
11	1		*TAILGATE INNER LOCK	Dented	560.70 FL	*560.70 FL
12	2		*TAILGATE HINGE	Serviceable	120.80 FL	*- FL
13	1		*TAILGATE WINDSCREEN GLASS	Shattered	1,120.80 FL	*1,120.80 FL
14	1		*TAILGATE WINDSCREEN GLASS MOULDING	Necessary	60.40 FL	*60.40 FL
15	1		*TAILGATE LOGO	Necessary	65.00 FL	*65.00 FL
16	1		*TAILGATE EMBLEM FORESTER & XT	Necessary	72.30 FL	*72.30 FL
17	1		*TAILGATE INNER TRIM BOARD	Distorted	190.80 FL	*190.80 FL
18	1		*TAILGATE INNER RH SIDE GARNISH	Serviceable	25.00 FL	*- FL
19	1		*TAILGATE WIPER MOTOR	Serviceable	216.30 FL	*- FL
20	1		*TAILGATE WIPER ARM	Serviceable	43.20 FL	*- FL
21	1		*TAILGATE WIPER BLADE	Serviceable	36.30 FL	*- FL
22	1		*TAILGATE INNER TOP CENTRE GARNISH	Cracked	160.30 FL	*160.30 FL
23	1		*TAILGATE RH TOUCH SENSOR	Distorted/Dented	360.30 FL	*360.30 FL
24	1		*TAILGATE NUMBER PLATE LAMP GARNISH	Cracked	49.50 FL	*49.50 FL
25	2		*TAILGATE NO PLATE LAMP	Serviceable	48.60 FL	*- FL
26	1		*TAILGATE THIRD BRAKE LAMP	Cut	170.50 FL	*170.50 FL
27	1		*REAR END PANEL	Bent	288.30 FL	*288.30 FL
28	1		*REAR END PANEL INNER TOP GARNISH	Mtg Cracked	40.30 FL	*40.30 FL
29	1		*REAR SPARE TYRE CENTRE TOOL SPONGE	Cracked	122.00 FL	*122.00 FL
30	1		*REAR SPARE TYRE RH SIDE SPONGE	Cracked	32.40 FL	*32.40 FL
31	1		*REAR RH FENDER	Buckled	960.80 FL	*960.80 FL
32	1		*REAR RH FENDER INNER TRIM (LOWER)	Cracked	228.40 FL	*228.40 FL
33	1		*REAR RH FENDER QUARTER GLASS MOULDING	Mtg Necessary	360.80 FL	*360.80 FL
34	1		*REAR RH MUFFLER	Bent	608.00 FL	*608.00 FL
35	1		*REAR RH MUFFLER END CHROME	Dented	82.00 FL	*82.00 FL
36	2		*REAR RH MUFFLER RUBBER MOUNTINGS	Torn	34.00 FL	*34.00 FL
37	1		*REAR RH FENDER INNER TRIM (UPPER)	Buckled	125.00 FL	*125.00 FL
38	1		*REAR RH MUFFLER HEAT SHIELD	Bent	67.30 FL	*67.30 FL
39	1		*EXHAUST MID PIPE	Bent	880.00 FL	*880.00 FL
40	1		*TAILGATE INNER RUBBER (50%)	Distorted	96.64 FS	*60.40 FS
41	1		*REAR NUMBER PLATE	Dented	35.00 FS	*35.00 FS
42	1		*REAR END PANEL SEALANT	Necessary	40.00 FS	*30.00 FS
43	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
44	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
45	1		*REAR RH FENDER QUARTER GLASS SEALANT	Necessary	30.00 FS	*30.00 FS
46	1		*REAR WINDSCREEN GLASS TINTED FILM	Necessary	180.00 FS	*150.00 FS

Report was unsubmitted during this print-out.

9/10/21, 11:08 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*TAILGATE EMBLEM SUBARU SYMMETRICAL & AWD	Necessary	72.30 FL	*72.30 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					11,064.04	10,477.30
- List Item Discount on L Items 20.00/20.00% (S\$)					2,088.48	1,986.38
Total Parts (S\$)					8,975.56	8,490.92
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING (FROM SCENE TO OTHER WORKSHOP)-BY OWNER	New	130.00	130.00
2	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
3	REMOVE & REFIX REAR RH FENDER QUARTER GLASS	New	50.00	50.00
4	REMOVE & REFIX REAR BUMPER & ATTACHMENTS, TAILLAMPS, TAILGATE, SPOILER & ATTACHMENTS; TO CUT, WELD & RENEW REAR END PANEL, REAR RH FENDER; KNOCKING & REPAIR REAR RH CHASSIS FRAME, REAR SPARE TYRE PANEL & REALIGN THE SAME	New	1,500.00	1,300.00
5	PUTTY & RESPRAY REAR BUMPER, REINFORCEMENT, REVERSE SENSORS, TAILGATE & SPOILER, REAR BOTH FENDERS, REAR RH DOOR, REAR END PANEL, REAR SPARE TYRE PANEL, RH CHASSIS FRAME & ALL AFFECTED AREAS	New	1,200.00	1,100.00
6	REMOVE & REFIX REAR EXHAUST MUFFLER & REALIGN THE SAME	New	80.00	60.00
7	REMOVE & REFIX SEAT, CARPET, ROOF LINING TO FACILITATE REPAIR	New	150.00	120.00
8	RUSTPROOFING	New	120.00	90.00
Gross Labour Cost (\$\$)			3,350.00	2,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >