

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG21005264/BPA3Q2

Date:

18/08/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2070110001

Claimant Vehicle No : SJT1115Y**Insured Vehicle No :**

SJR9699L

Date of Loss: 26/04/2021

Nature of Claim:

TP

Claim No:

6866733041SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJT1115Y**

Make & Model: KIA CERATO FORTE, 1.6 SX AT ABS D/AB 2WD 4DR (A)

Engine No:

G4FC9H283564

Reg. Date: 24/09/2009 (Man. Year: 2009)

Chassis No:

KNAFW411MA5113863

Colour: Black

Odometer:

110664 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size:

215/45 R17

Front Left Side: Falken 6 mm

Rear Left Side:

Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side:

Falken 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,773.46	420.67	3,352.79	88.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	460.00	1,440.00	75.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,673.46	880.67	4,792.79	84.48
Approved Total (Overridden) (S\$)		700.00		

(S\$)	5,673.46	700.00	4,973.46	87.66
+ GST 7.00/7.00% (S\$)	397.14	49.00	348.14	87.66
Nett Amount (S\$)	6,070.60	749.00	5,321.60	87.66
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
Nett Liability (S\$)		1,070.00		

INSPECTION

Date of Assignment: 28/04/2021

Date Inspected: 29/04/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)
 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
 Singapore 575722

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	988.00 FL	*- FL
2	2		*REAR BUMPER SIDE RETAINER	Necessary	177.20 FL	*70.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Damaged	458.00 FL	*- FL
4	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Damaged	448.00 FL	*- FL
5	1		*REAR BUMPER INNER SPONGE	Not Damaged	187.00 FL	*- FL
6	1		*REAR BUMPER DIFFUSER	Dislodged	489.20 FL	*286.30 FL
7	4		*REAR BUMPER REVERSE SENSOR	Not Damaged	1,032.00 FL	*- FL
8	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
9	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
10	1		*REAR BUMPER DIFFUSER CLIPS	Necessary	50.00 FS	*30.00 FS
11	4		*REAR BUMPER REVERSE SENSOR SEAL	Necessary	192.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,151.40	456.30
- List Item Discount on L Items 10.00/10.00% (\$)	377.94	35.63
Total Parts (\$)	3,773.46	420.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
2	CHECK WIRING	New	100.00	0.00
3	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
4	PANEL BEATING	New	600.00	200.00
5	RUST PROOFING	New	200.00	0.00
6	SPRAY PAINTING	New	600.00	200.00
Gross Labour Cost (\$\$)			1,900.00	460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >