

SMX4336A.

Hyundai Avante.

KMHLN41ETMU111891

TP AXA.

Xiao Chen.

Front Fender RH	Dented	1227.70	✓
Front Fender Inner Garish.	Reh	94.60	✓
Front RH Door	Dented	1993	✓
Front RH Door Weatherstripe	Re	112.30	×
Front RH Door Lock	Re	191.50	×
Front RH Door Check	Re	39.80	✓
Front RH Mudflap	Re	23	✓

3378.10

2702.48

Panel Bending

~~800~~ 400

Spray Painting.

~~700~~ 400

Wiring.

~~50~~ 30

910.

To transfer door fittings.

~~150~~ 80.

Total: 3612.48
(P/P)

04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: