

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005267/KGA3Q2**Date:** 14/07/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLX7204P**Insured Vehicle No :** SJR5325S

Date of Loss: 25/04/2021

Nature of Claim: TP

Claim No: 9986641519SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLX7204P**

Make & Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 2NR5210856

Reg. Date: 09/04/2018 (Man. Year: 2018)

Chassis No: MR2B23F3401118304

Colour: Metallic Red

Odometer: 121231 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size:

185/60 R15

Front Left Side: Maxxis 7 mm

Rear Left Side:

Maxxis 7 mm

Front Right Side: Maxxis 7 mm

Rear Right Side:

Maxxis 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,207.09	1,981.86	225.23	10.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	1,260.00	140.00	10.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,607.09	3,241.86	365.23	10.13
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	3,607.09	2,600.00	1,007.09	27.92
+ GST 7.00/7.00% (S\$)	252.50	182.00	70.50	27.92
Nett Amount (S\$)	3,859.59	2,782.00	1,077.59	27.92
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,284.00		

INSPECTION

Date of Assignment: 28/04/2021

Date Inspected: 17/05/2021 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	489.10 FL	*489.10 FL
2	1		*REAR BUMPER SIDE RETAINER	N/S Distorted	267.80 FL	*133.90 FL
3	6		*REAR BUMPER CLIP	Necessary	21.00 FL	*21.00 FL
4	1		*REAR BOOT	Bent	611.90 FL	*611.90 FL
5	1		*REAR BOOT LOGO	Necessary	50.20 FL	*50.20 FL
6	1		*REAR BOOT EMBLEM -VIOS	Necessary	49.50 FL	*49.50 FL
7	1		*REAR BOOT EMBLEM -E	Necessary	39.80 FL	*39.80 FL
8	1		*REAR BOOT INNER LOCK	Dented	360.42 FL	*360.42 FL
9	1		*REAR BOOT INNER RUBBER	Serviceable	166.40 FL	*- FL
10	1		*REAR PANEL	Bent	620.00 FL	*620.00 FL
11	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
					Sub Total (\$)	2,876.12 2,575.82
					- List Item Discount on L Items 25.00/25.00% (\$)	669.03 593.96
					Total Parts (\$)	2,207.09 1,981.86

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEATING	New	650.00	600.00
2	TO PUTTY AND RESPRAY ON REAR BOOT ,REAR PANEL ,REAR BUMPER	New	750.00	660.00
Gross Labour Cost (\$)			1,400.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >