



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2103942

INV Date 07/06/2021

Reference CC4/LPC21005270/Apa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMU 9105H
Insured Veh. GX 1523S
Claim No. 21/21/21/VC05/024493
Policy No. Z21VC05006798
Accident Date 25/04/2021
Inspection Date 28/04/2021

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21005270/Apa3q2 Date: 07/06/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GX 1523S	Veh. Inspected	SMU 9105H	
Policy No.	Z21VC05006798	Coverage (\$)	0.00	
Claim No.	21/21/21/VC05/024493	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	27/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A6	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WAUZZZ4GXGN038998	Colour	BLACK	
Odometer	85062 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/30 R19	MICHELIN	6 mm	
L/H Front Tyre	275/30 R19	MICHELIN	6 mm	
R/H Rear Tyre	275/30 R19	MICHELIN	6 mm	
L/H Rear Tyre	275/30 R19	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/04/2021	Inspection Date	28/04/2021	
Survey held at	GLOCKEWERKE 21 KAKI BUKIT ROAD 4 #01-02 SYNERGY @ KB SINGAPORE 417810			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMU 9105H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	2,500.00	2,500.00
1	FRONT LEFT HEADLAMP	CRACKED	2,100.00	2,100.00
1	FRONT LEFT HEADLAMP BRACKET	NOT NECESSARY	168.00	-
1	FRONT LEFT FENDER	TO REPAIR SEE LABOUR	975.00	-
1	FRONT BONNET	DENTED	2,850.00	2,850.00
1	FRONT INNER BUMPER PLASTIC TRIM	NOT NECESSARY	90.00	-
	LESS 5% DISCOUNT		-434.15	-
	LESS 10% DISCOUNT		-	-745.00
			8,248.85	6,705.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
2	FRONT PDC SENSOR @\$100.00 (SN)	NOT NECESSARY	200.00	-
1	COATING (SN)	NECESSARY	400.00	400.00
			630.00	430.00
	<u>LABOUR</u>			
	DIAGNOSE ,REPLACE AND REPAIR TO RECTIFY ELECTRICAL SYSTEM FOR PROPER FUNCTION .		60.00	30.00
	TO PROVIDE WORKMANSHIP LABOUR TO REMOVE DAMAGE PARTS FOR ASSESSMENT AT TO NEW BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ADJUST STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT FROM THE ACCIDENT .INCLUSIVE OF THE REPAIR OF FRONT LEFT FENDER .		800.00	400.00
	TO RE-SPRAY PAINTINF FOR CHARGE BODYPARTS ,REPAIR PORTION AND WHERE CONSISTENT FROM THE ACCIDENT.		1,000.00	600.00
			1,860.00	1,030.00
	GRAND TOTAL		10,738.85	8,165.00



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,500.00
---	--	--	-----------------

Report Ref No. CC4/LPC21005270/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMU 9105H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMU 9105H

RE-INSPECTION

