

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD	Ref	: (	CS3/LPC21005271/Gqf3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date	e:	17/05/2021	
			Cod	le:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SLB 608U	Veh. Inspected	;	SMX 8006B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	20/21/21/VP05/024504	Excess (\$)	(	0.00	
	Assign From	ONG LI LI	Assign Date	:	29/04/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA NOAH 1.8X	c.c	,	1797	
	Engine No.	HIDDEN	Year of Reg.	:	2021	
	Chassis No.	ZWR800436226	Colour		BLACK	
	Odometer	15639 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification	;	STANDARD ALLOY RIM	
	General	GOOD				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	YOKOHAMA		7 mm	
	L/H Front Tyre	195/65 R15	YOKOHAMA		7 mm	
	R/H Rear Tyre	195/65 R15	YOKOHAMA		7 mm	
	L/H Rear Tyre	195/65 R15	YOKOHAMA		7 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR O/S PORTION.				
5.	General Information					
	Accident Date	27/04/2021	Inspect Date / Time	• :	29/04/2021 ( 01:00 PM )	
	Survey held at	APEX MOTORING				
		25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGPORE 417800				
5a.	•	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC21005271/Gqf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

**Automotive Assessor**