

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

682.64

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMX 4545M

**RECOMMENDED COST OF REPAIRS** 

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	MIRROR ASSY,R (SN)	CRACKED	217.72	217.72
1	CAP,R SKULL (SN)	BROKEN / MISSING	44.92	44.92
			312.64	282.64
	<u>LABOUR</u>			
	INSPECT FR LIGHTING MECHANISMS & FOCUS.		180.00	80.00
	RESET VEHICLE SMART ENTRY SYSTEM.	NOT NECESSARY	520.00	-
	RENEW WING MIRROR SET.		800.00	200.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (1P).		600.00	120.00
			2,100.00	400.00
	GRAND TOTAL		2,412.64	682.64

Report Ref No. CS/SMR21005281/Uuf3n2

CHUA KANG SENG

**Licensed Appraiser**