

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 3649S

| Qty | Description of Parts   | Condition               | Estimate By<br>Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|-------------------|
|     | REPLACEMENT OF PARTS   |                         |                               |                   |
| 1   | REAR BOOT  | BENT                    | 1,378.25                      | 1,378.25          |
| 1   | REAR BOOT LOCK   | BENT                    | 974.20                        | 974.20            |
| 1   | SET REAR WINDSCREEN MOULDING   | NECESSARY               | 307.60                        | 307.60            |
| 1   | REAR END PANEL TRIM  | CRACKED                 | 438.30                        | 438.30            |
| 1   | REAR BUMPER  | DEFORMED                | 1,453.20                      | 1,453.20          |
| 1   | REAR BUMPER RETAINER LH  | NOT NECESSARY           | 100.70                        | -                 |
| 1   | REAR BUMPER SENSOR   | NOT WORKING             | 397.80                        | 397.80            |
| 1   | REAR BUMPER SPONGE   | CRACKED                 | 118.70                        | 118.70            |
| 10  | REAR BUMPER CLIPS @\$5.78  | NECESSARY               | 57.80                         | 57.80             |
| 1   | REAR FLOOR PANEL (NPA)   | TO REPAIR SEE<br>LABOUR | -                             | -                 |
| 1   | REAR FENDER LH (NPA)   | TO REPAIR SEE<br>LABOUR | -                             | -                 |
| 1   | REAR PANEL (NPA)   | TO REPAIR SEE<br>LABOUR | -                             | -                 |
|     | LESS 25% DISCOUNT  |                         | -1,306.64                     | -1,281.46         |
|     |  |                         | 3,919.91                      | 3,844.39          |
|     | SPECIAL NETT ITEMS   |                         |                               |                   |
| 1   | REAR WINDSCREEN SEALANT (SN)   | NECESSARY               | 80.00                         | 60.00             |
|     | , ,  |                         | 80.00                         | 60.00             |
|     | <u>LABOUR</u>  |                         |                               |                   |
|     | TO REPAIR REAR END PANEL, REAR FLOOR PANEL<br>REMOVE & REPLACE DAMAGED PARTS, TO<br>STRAIGHTEN AND REALIGN AFFECTED AREAS.<br>INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL,<br>REAR FENDER LH AND REAR PANEL. |                         | 600.00                        | 400.00            |
|     | TO SPRAY REAR BOOT, REAR END PANEL, REAR FLOOR PANEL, REAR BUMPER AND AFFECTED AREAS.  |                         | 750.00                        | 400.00            |
|     | TO REMOVE & REFIX REAR WINDSCREEN GLASS.   |                         | 130.00                        | 120.00            |
|     | TO REMOVE & REFIX BOOT MECHANISM.  |                         | 60.00                         | 40.00             |
|     |  |                         | 1,540.00                      | 960.00            |
|     | GRAND TOTAL  |                         | 5,539.91                      | 4,864.39          |

Report Ref No. CS/SMR21005282/R1vf3e2



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS | 3,800.00 |
|--------------------------------------|----------|
| (TO ITS PRE-ACCIDENT CONDITION)      | ·        |

Report Ref No. CS/SMR21005282/R1vf3e2

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

P

**ANG BRYAN TANI** 

**Automotive Assessor / Investigator**