



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : WH0659
Vehicle No. : SLJ9576B
Make & Model : NISSAN QASHQAI

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
	Boot lid <i>Repair</i> x		2964.00	
	Boot lid emblem "Qashqai" <i>MC</i>		87.00	
	Boot lid logo badge x <i>NN</i>		70.00	
	Rear bumper <i>Re</i>		771.00	
	Rear bumper side retainer LH/RH@ 2*\$37 <i>LH/Re RH x NN</i>		74.00	
	Rear bumper towing cover x <i>NN</i>		37.00	
	Rear bumper sponge ?		127.00	
	Rear reinforcement ?		692.00	
	End Panel (Repair refer to labor) <i>x Repair</i>		0.00	
Part Items Total:			4822.00	
			-30%	
			-1446.60	
			3375.40	
SPECIAL NETT ITEMS				
1	Rear reversor Sensor ?		200.00	
1	Rear bumper clips <i>MC</i>		35.00	
1	Windscreen sealant x <i>NN</i>		60.00	
SN Items Total:			295.00	
Total Parts:			3670.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	:	WH0659
Vehicle No.	:	SLJ9576B
Make & Model	:	NISSAN QASHQAI

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	600.
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00	X 1/2 m
4	To perform anti-rust treatment on affected areas	60.00	X
5	To remove and replace Rear Reverse Sensor	100.00	40.
6	To carried out remove and refix rear windscreen sealant	150.00	X NN
7	To remove and refit/replace rear compartment fitting, trimmings, garnish and etc	100.00	60.
Labour Total :		2070.00	
TOTAL (PARTS & LABOUR):		5740.40	

4 Days.
part by mt.
before paint photos.
Guo Qiang - 8288 0282
Guo Qiang @ lkk auto. com
03/5/21.