

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21005285/AQCN2**Date:** 14/09/2021**REFERENCE**

Insured/Claimant:	TAN GEOK CHEONG	Policy No:	2070124741	
Date of Loss:	26/04/2021	Nature of Claim:	OD	Claim No: 0727605263SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK8337M	Engine No:	CZD898334
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF31L1118993
Reg. Date:	25/08/2020 (Man. Year: 2020)	Odometer:	6521 km
Colour:	Red		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$155,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65R17	Rear Tyre Size:	215/65R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,358.00	15,846.24	17,511.76	52.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,632.00	6,022.00	6,610.00	52.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,990.00	21,868.24	24,121.76	52.45
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	45,590.00	21,468.24	24,121.76	52.91
+ GST 7.00/7.00% (S\$)	3,191.30	1,502.78	1,688.52	52.91
Nett Amount (S\$)	48,781.30	22,971.02	25,810.28	52.91

INSPECTION

Date of Assignment:	29/04/2021	
Date Inspected:	28/04/2021	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	11.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,161.00 FS	*1,728.40 FS
2	1		*FRONT BUMPER UPPER CLOSING ELEMENT	O/s Cracked	118.00 FS	*46.64 FS
3	1		*FRONT BUMPER GRILLE-CENTER	Cracked	217.00 FS	*173.20 FS
4	1		*FRONT BUMPER COVER	Dented	51.00 FS	*40.80 FS
5	1		*FRONT BUMPER GRILLE-LH/RH	O/s Deformed	220.00 FS	*88.00 FS
6	1		*FRONT BUMPER LOWER CLOSING ELEMENT	Deformed	190.00 FS	*151.60 FS
7	1		*FRONT BUMPER SPOILER	Deformed	383.00 FS	*306.40 FS
8	1		*FRONT BUMPER BRACKET	Not Necessary	21.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Deformed	153.00 FS	*122.00 FS
10	1		*FRONT RADIATOR GRILLE	Cracked	1,433.00 FS	*1,146.40 FS
11	1		*FRONT RADIATOR STRIKER PLATE	Cracked	244.00 FS	*194.80 FS
12	1		*FRONT RADIATOR COVER CAP	Not Necessary	45.00 FS	*- FS
13	1		*FRONT RADIATOR BRACKET	Not Necessary	41.00 FS	*- FS
14	1		*FRONT IN BOARD CAMERA	Not Necessary	1,141.00 FS	*- FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	102.00 FS	*81.60 FS
16	1		*FRONT BUMPER CARRIER	Bent	916.00 FS	*732.40 FS
17	1		*FRONT BUMPER GUIDE SECTION-LH/RH	O/s Cracked	78.00 FS	*30.48 FS
18	1		*FRONT BUMPER REINFORCEMENT COVER	Cracked	123.00 FS	*98.00 FS
19	1		*AIR CONDITIONER STICKER	Necessary	8.00 FS	*5.68 FS
20	1		*FRONT LOW TONE HORN-RH	Not Necessary	130.00 FS	*- FS
21	1		*FRONT LOW TONE HORN SPRING HACKLE-RH	Not Necessary	22.00 FS	*- FS
22	3		*FRONT PARKING AID SENSOR	Damaged	732.00 FS	*585.36 FS
23	1		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
		4 Pcs				
24	1		*FRONT BUMPER WIRING SET	Snapped	676.00 FS	*540.80 FS
25	1		*FRONT FENDER-RH	Repair	1,286.00 FS	*- FS
26	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	63.00 FS	*- FS
27	1		*FRONT FENDER BRACE-RH	Not Necessary	88.00 FS	*- FS
28	1		*FRONT FENDER BRACKET-RH	Not Necessary	32.00 FS	*- FS
29	1		*FRONT WHEEL HOUSING LINER (NPA)	Not Necessary	0.00 FS	*- FS
30	1		*FRONT FENDER COVER-RH	Not Necessary	16.00 FS	*- FS
31	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	101.00 FS	*- FS
32	1		*FRONT BONNET	Dented	3,058.00 FS	*2,806.40 FS
33	2		*FRONT BONNET LID HINGE-LH/RH	Not Necessary	146.00 FS	*- FS
34	1		*FRONT BONNET ATTACHMENT PARTS	Not Necessary	296.00 FS	*- FS
35	1		*FRONT BONNET STRIKER-RH	Not Necessary	110.00 FS	*- FS
36	1		*FRONT BONNET SOUND ABS	Not Necessary	219.00 FS	*- FS
37	1		*FRONT BONNET IMPACT PROTECTION-CENTER	Necessary	28.00 FS	*21.84 FS
38	1		*FRONT BONNET BOWDEN CABLE-CENTER	Necessary	58.00 FS	*46.00 FS
39	1		*FRONT BONNET LID LOCK	Not Necessary	214.00 FS	*- FS
40	1		*FRONT BONNET RELEASE ELEMENT	Not Necessary	58.00 FS	*- FS
41	1		*FRONT BONNET RELEASE LEVER	Not Necessary	14.00 FS	*- FS
42	1		*FRONT BONNET RELEASE COVER	Not Necessary	10.00 FS	*- FS
43	1		*HEADLIGHT MOUNTING-LH/RH	O/s Cracked	236.00 FS	*94.40 FS
44	1		*HEADLIGHT-RH	Cut	5,589.00 FS	*4,471.20 FS
45	1		*HEADLIGHT POWER MODULE	Not Necessary	758.00 FS	*- FS
46	1		*HEADLIGHT LED	Not Necessary	781.00 FS	*- FS
47	1		*HEADLIGHT HOSE-RH	Not Necessary	24.00 FS	*- FS
48	1		*HEADLIGHT LIFT CYLINDER-RH	Not Necessary	210.00 FS	*- FS
49	1		*HEADLIGHT LIFT CYLINDER HOSE	Cut	80.00 FS	*63.44 FS
50	2		*FRONT WHEEL ARCH COVER-LH/RH	Necessary	536.00 FS	*428.80 FS
51	1		*FRONT RADIATOR LOCK CARRIER	Cracked	1,272.00 FS	*1,017.60 FS
52	1		*A/C CONDENSER	Dented	551.00 FS	*440.80 FS
53	1		*A/C CONDENSER SEAL RING	Not Necessary	10.00 FS	*- FS
54	1		*A/C CONDENSER SEAL RING	Not Necessary	7.00 FS	*- FS
55	1		*A/C COMPRESSOR REFRIGERANT LINE	Not Necessary	337.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*A/C COMDENSER REFRIGERANT LINE	Not Necessary	330.00 FS	*- FS
57	1		*TEMPERATURE SENSOR HOLDER	Not Necessary	7.00 FS	*- FS
58	1		*FRONT RADIATOR TEMPERATURE SENSOR	Not Necessary	59.00 FS	*- FS
59	1		*FRONT RADIATOR INTER COOLER	Not Necessary	920.00 FS	*- FS
60	1		*FRONT RADIATOR	Not Necessary	1,035.00 FS	*- FS
61	1		*FRONT RADIATOR FAN	Not Necessary	1,529.00 FS	*- FS
62	1		*COOLANT	Necessary	269.00 FS	*214.56 FS
		6 Pcs				
63	1		*FRONT RADIATOR AIR GUIDE-LH/RH	O/s Cracked	76.00 FS	*29.76 FS
64	1		*FRONT RADIATOR UPPER AIR GUIDE	Cracked	42.00 FS	*33.04 FS
65	1		*FRONT RADIATOR LOWER AIR GUIDE	Deformed	42.00 FS	*33.04 FS
66	1		*FRONT RADIATOR INTAKE CONNECTION	Not Necessary	610.00 FS	*- FS
67	1		*FRONT RADIATOR SEAL	Not Necessary	14.00 FS	*- FS
68	1		*FRONT RADIATOR INTER COOLER	Not Necessary	775.00 FS	*- FS
69	1		*FRONT RADIATOR INTER COOLER SEAL	Not Necessary	17.00 FS	*- FS
70	1		*FRONT RADIATOR INTER COOLER GASKET	Not Necessary	14.00 FS	*- FS
71	1		*THROTTLE VALVE ADAPTER	Not Necessary	824.00 FS	*- FS
72	1		*THROTTLE VALVE ADAPTER SEAL	Not Necessary	17.00 FS	*- FS
73	1		*INTAKE PIPE GASKET	Not Necessary	14.00 FS	*- FS
74	1		*PREASURE PIPE SEAL RING	Not Necessary	18.00 FS	*- FS
75	1		*INTAKE PIPE RETAINING BAR	Not Necessary	15.00 FS	*- FS
76	1		*INTAKE PIPE AIR GUIDE	Not Necessary	56.00 FS	*- FS
77	1		*INTAKE PIPE AIR GUIDE COVER	Not Necessary	29.00 FS	*- FS
78	1		*AIR FILTER	Not Necessary	239.00 FS	*- FS
79	1		*AIR FILTER AIR GUIDE	Not Necessary	20.00 FS	*- FS
80	1		*WATER DRAINAGE HOSE	Not Necessary	21.00 FS	*- FS
81	1		*INTAKE AIR GUIDE	Not Necessary	34.00 FS	*- FS
82	1		*INTAKE AIR DUCT	Not Necessary	47.00 FS	*- FS
83	1		*INTAKE MANIFOLD	Not Necessary	121.00 FS	*- FS
84	1		*NOISE INSULATION	Not Necessary	397.00 FS	*- FS
85	1		*FRONT BUMPER PLATE	Dented	60.00 FS	*60.00 FS
86	1		*SUNDRIES	Necessary	300.00 FS	*12.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	33,358.00	15,846.24
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER,CHARGED AIR COOLER AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM & REGAS (R1234)	New	1,700.00	1,200.00
4	TO RENEW THROTTLE BODY AND OTHER ENGINE COMPONENTS	New	480.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET,RHS FRONT FENDER AND RHS HEADLIGHT.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	5,600.00	2,250.00
6	TO RESPRAY FRONT BUMPER,RHS FRONT FENDER,BONNET AND HINGES	New	3,500.00	1,650.00
7	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			12,632.00	6,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >