

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21005286/DVF3N2**Date:** 31/08/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00145772000

**Claimant Vehicle
No :** SKC1990P**Insured Vehicle
No :** SKF2313Y

Date of Loss: 15/04/2021

Nature of Claim: TP

Claim
No: SNM21D202469/C2/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SKC1990P**

Make & Model: VOLKSWAGEN SCIROCCO, 1.4 (A)

Engine No: CAV231291

Reg. Date: 23/11/2010 (Man. Year: 2010)

Chassis No: WVVZZZ13ZBV015141

Colour: Yellow

Odometer: 180828 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35R19

Rear Tyre Size:

235/35R19

Front Left Side: Michelin 5 mm

Rear Left Side:

Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side:

Michelin 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 11,712.19 | 3,100.00 | 8,612.19 | 73.53 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,800.00 | 1,100.00 | 3,700.00 | 77.08 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 16,512.19 | 4,200.00 | 12,312.19 | 74.56 |
| Approved Total (Overridden) (S\$) | | 3,300.00 | | |
| (S\$) | 16,512.19 | 3,300.00 | 13,212.19 | 80.01 |
| + GST 7.00/7.00% (S\$) | 1,155.85 | 231.00 | 924.85 | 80.01 |
| Nett Amount (S\$) | 17,668.04 | 3,531.00 | 14,137.04 | 80.01 |

INSPECTION

Date of Assignment: 29/04/2021

Date Inspected: 12/05/2021 Inspected At:

JWG International Pte Ltd (HQ)

Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK

AutoPoint

Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 30 Aug 2021) |
| Parts: | M1-COUPE | VOLKSWAGEN SCIROCCO 1.4 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SKC1990P) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------------|---------------|--|---------------------------|
| 1 | 1 | | *HEAD LAMP RH | Not Necessary | 2,569.10 FL | *- FL |
| 2 | 1 | | *FRONT BONNET | Not Necessary | 2,800.00 FS | *- FS |
| 3 | 1 | | *FRONT BUMPER DAYTIME RUNNING LIGHTS | Not Necessary | 1,600.00 FS | *- FS |
| 4 | 1 | | *FRONT FENDER GARNISH | Cut | 2,600.00 FS | *1,300.00 FS |
| 5 | 1 | | *FRONT BUMPER CARBON FIBER | Cut | 2,400.00 FS | *1,800.00 FS |
| | | | | | Sub Total (\$\$) | 11,969.10 3,100.00 |
| | | | | | - List Item Discount on L Items 10.00/10.00% (\$\$) | 256.91 0.00 |
| | | | | | Total Parts (\$\$) | 11,712.19 3,100.00 |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS | New | 2,000.00 | 500.00 |
| 2 | TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS | New | 2,000.00 | 600.00 |
| 3 | TO TUFF COAT DAMAGED AREAS | New | 300.00 | 0.00 |
| 4 | TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS | New | 200.00 | 0.00 |
| 5 | TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS | New | 300.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 4,800.00 | 1,100.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >