

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21005295/KBS3Q2
Date: 14/07/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMU4299P	Insured Vehicle No :	SLM4404G
Date of Loss:	27/04/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001925

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU4299P		
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Engine No:	L15B6021916
Reg. Date:	13/08/2020 (Man. Year: 2019)	Chassis No:	GK82101635
Colour:	Metallic Purple	Odometer:	12021 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,684.04	2,839.52	844.52	22.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	1,230.00	1,140.00	48.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,054.04	4,069.52	1,984.52	32.78
Approved Total (Overridden) (S\$)		3,250.00		

(S\$)	6,054.04	3,250.00	2,804.04	46.32
+ GST 7.00/7.00% (S\$)	423.78	227.50	196.28	46.32
Nett Amount (S\$)	6,477.82	3,477.50	3,000.32	46.32
+ Car Rental (6.0 x S\$120.00/day + 7.00% GST) (S\$)		770.40		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,255.35		
Global Sum Settlement (S\$)		4,200.00		

INSPECTION

Date of Assignment: 29/04/2021

Date Inspected: 30/04/2021

Estimated Period of Repair: 4.0 days

Inspected At: Optima Werkz Pte Ltd (HQ)
6 Kung Chong Road
Singapore 159143

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Jul 2021)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU4299P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,217.00 FL	*1,193.40 FL
2	1		*REAR TAILGATE INNER TRIM BOARD	Mtg Cracked	370.00 FL	*370.00 FL
3	1		*REAR TAILGATE SHUTTLE EMBLEM	Not Necessary	75.00 FL	*- FL
4	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	65.00 FL	*65.00 FL
5	1		*REAR WINDSCREEN MLDG	Necessary	120.00 FL	*120.00 FL
6	1		*REAR TAILGATE WEATHERSTRIP	Dented	168.50 FL	*168.50 FL
7	1		*REAR BUMPER	Mtg Distorted	1,189.00 FL	*936.50 FL
8	1		*REAR BUMPER CHROME	Necessary	178.00 FL	*178.00 FL
9	1		*END PANEL	Repair	560.80 FL	*- FL
10	1		*END PANEL TOP COVER	Mtg Cracked	155.50 FL	*155.50 FL
11	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
12	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*50.00 FS
13	1		*REAR BUMPER REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
14	1		*REAR END PANEL TOP COVER CLIPS	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,503.80	3,476.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	819.76	637.38
Total Parts (\$\$)	3,684.04	2,839.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX REAR ACCIDENT AREA	New	800.00	500.00
2	LABOUR CHARGES TO SUPPLY PAINT FOR REAR ACCIDENT AREA	New	800.00	450.00
3	LABOUR CHARGES TO REMOVE AND REFIX REAR WINDSCREEN GLASS	New	150.00	120.00
4	LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER MECHANISM	New	120.00	60.00
5	LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR	New	100.00	50.00
6	TO APPLY ANTI-RUST	New	150.00	30.00
7	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	150.00	0.00
8	LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	100.00	20.00
Gross Labour Cost (S\$)			2,370.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >