

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005297/KGS3Q2
Date: 26/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070110931
Claimant Vehicle No :	SKN1223M	Insured Vehicle No :	SMT9140K
Date of Loss:	26/04/2021	Nature of Claim:	TP
		Claim No:	9017839317SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN1223M		
Make & Model:	PORSCHE PANAMERA, 3.6 PDK (A)	Engine No:	B03695
Reg. Date:	10/02/2011 (Man. Year: 2010)	Chassis No:	WP0ZZZ97ZBL003056
Colour:	Black	Odometer:	77787 km
Engine Capacity:	3605 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/45Z R19	Rear Tyre Size:	285/40Z R19
Front Left Side:	Michelin 3 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 3 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,004.30	1,937.52	2,066.78	51.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,000.00	800.00	44.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,804.30	2,937.52	2,866.78	49.39
+ GST 7.00/7.00% (S\$)	406.30	205.63	200.67	49.39

Nett Amount (\$\$)	6,210.60	3,143.15	3,067.45	49.39
+ Loss of Use (3.0 x S\$150.00/day) (\$\$)		450.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		3,600.60		

INSPECTION

Date of Assignment: 29/04/2021

Date Inspected: 03/05/2021

Inspected At:

Motor Edgevantage Pte Ltd (HQ)
 160 Sin Ming Drive, Sin Ming AutoCity #03-01/02
 Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Recommended Parts

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE INSTALL ,REPLACEMENT FRONT BUMPER & FRONT FENDER LABOUR TO TRANSFER BUMPER PARTS	New	800.00	400.00
2	TO PUTTY ,REPAIR & SRPAY PAINTING FRONT RH FENDER & FRONT BUMPER ASSEMBLY	New	1,000.00	600.00
Gross Labour Cost (\$\$)			1,800.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >