#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way, #09-16

Our File No: CC3/AIG21005300/ATCE2

Singapore 079120 Date: 03/09/2021

**REFERENCE** 

Insured/Claimant: LUO WUQIONG Policy No: 2070125657

Date of Loss: 26/04/2021 Nature of Claim: OD Claim No: 7447802383SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMU6923H

Make & Model: AUDI Q2, 999cc 1.0 TFSI S TRONIC (A) Engine No: CHZC33089

Reg. Date: 25/08/2020 (Man. Year: 2019) Chassis No: WAUZZZGA7KA084229

Colour: Grey Odometer: 4447 km

Engine Capacity: 999 cc
Market Value/New Car Price: \$\$115,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		8,464.00	753.20	7,710.80	91.10
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,152.00	1,242.00	2,910.00	70.09
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	12,616.00	1,995.20	10,620.80	84.19
	- Excess (S\$)	800.00	800.00	0.00	0.00
	(S\$)	11,816.00	1,195.20	10,620.80	89.88
	+ GST 7.00/7.00% (S\$)	827.12	83.66	743.46	89.89
	Nett Amount (S\$)	12,643.12	1,278.86	11,364.26	89.88

**INSPECTION** 

Date of Assignment: 29/04/2021

Date Inspected: 29/04/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Repair	1,042.00 FS	*- FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	347.00 FS	*- FS
3	1	*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	169.00 FS	*-FS
4	1	*FRONT BUMPER AIR GUIDE GRILLE END CAP - RH	Not Necessary	59.00 FS	*-FS
5	1	*FRONT BUMPER SPOILER	Cut	299.00 FS	*238.80 FS
6	1	*FRONT BUMPER CLOSING ELEMENT	Not Necessary	156.00 FS	*-FS
7	1	*FRONT FENDER WHEEL SPOILER - RH	Not Necessary	34.00 FS	*-FS
8	1	*FRONT WHEEL SPOILER ADAPTER - RH	Not Necessary	42.00 FS	*-FS
9	1	*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	36.00 FS	*- FS
10	1	*FRONT WHELE HOUSING LINER - RH	Not Necessary	196.00 FS	*-FS
11	1	*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	57.00 FS	*-FS
12	2	*FRONT WHEEL ARCH COVER - LH / RH	N/S Necessary / O/S Cut	644.00 FS	*514.40 FS
13	1	*HEADLIGHT MOUNTING - RH	Not Necessary	118.00 FS	*-FS
14	1	*HEADLIGHT - RH	Not Necessary	4,915.00 FS	*-FS
15	1	*SUNDRIES	Not Necessary	350.00 FS	*- FS
F=Fra	ınchise	part. S=SpcNett.	-		
			Total Parts (S\$)	8,464.00	753.20
		Report was unsubmitted during this	print-out.		

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENT. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY	New	360.00	0.00
	Gross Labour Cost (S\$)		4,152.00	1,242.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >