

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC3/AIG21005302/APS3Q2

Date:

12/10/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100395858

Claimant Vehicle No : SJT296P**Insured Vehicle No :**

SKD5366K

Date of Loss: 28/04/2021

Nature of Claim:

TP

Claim No:

9960752776SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJT296P**

Make & Model: AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)

Engine No:

CVK077267

Reg. Date: 29/03/2019 (Man. Year: 2019)

Chassis No:

WAUZZZF40KA043906

Colour: Black

Odometer:

41139 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size:

245/40 R18

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,887.24	6,957.36	5,929.88	46.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,102.00	4,382.00	6,720.00	60.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,989.24	11,339.36	12,649.88	52.73
+ GST 7.00/7.00% (S\$)	1,679.25	793.76	885.49	52.73

Nett Amount (S\$)	25,668.49	12,133.12	13,535.37	52.73
+ Car Rental (8.0 x S\$140.00/day + 7.00% GST) (S\$)		1,198.40		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		13,333.52		

INSPECTION

Date of Assignment: 04/05/2021

Date Inspected: 04/05/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	1,787.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	587.00 FS	*- FS
3	1		*FRONT BUMPER AIR GUIDE -LH	Not Necessary	63.00 FS	*- FS
4	1		*FRONT BUMPER SECURING STRIP	Not Necessary	36.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE GRILLE -LH	Not Necessary	135.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE SECTION -LH	Not Necessary	36.00 FS	*- FS
7	1		*FRONT DOOR -LH	Distorted	3,192.00 FS	*2,553.60 FS
8	1		*FRONT DOOR OUTER SEAL -LH	Necessary	205.00 FS	*164.00 FS
9	1		*FRONT DOOR BONDING AGENT	Necessary	49.00 FS	*38.48 FS
10	1		*FRONT DOOR CLEANING SOLUTION	Necessary	68.00 FS	*54.00 FS
11	1		*FRONT DOOR APPLICATOR	Not Necessary	8.00 FS	*- FS
12	1		*FRONT DOOR CATCH	Damaged	105.00 FS	*84.00 FS
13	1		*FRONT DOOR HANDLE TRIM PLATE	Damaged	88.00 FS	*69.92 FS
14	1		*FRONT DOOR HOUSING	Damaged	8.00 FS	*5.92 FS
15	1		*FRONT DOOR MOUNTING BAR	Cracked	164.00 FS	*130.80 FS
16	1		*FRONT MIRROR -LH	Not Necessary	1,089.00 FS	*- FS
17	1		*REAR DOOR -LH	Dented	3,192.00 FS	*2,553.60 FS
18	1		*REAR DOOR OUTER SEAL -LH	Necessary	205.00 FS	*164.00 FS
19	1		*REAR DOOR BODING AGENT	Not Necessary	49.00 FS	*- FS
20	1		*REAR DOOR CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
21	1		*REAR DOOR APPLICATOR	Not Necessary	8.00 FS	*- FS
22	1		*REAR DOOR SEALING STRIP	Not Necessary	17.00 FS	*- FS
23	1		*REAR DOOR CATCH	Not Necessary	120.00 FS	*- FS
24	1		*REAR DOOR WHEEL HOUSING LINER -LH	Not Necessary	240.00 FS	*- FS
25	1		*LHS REAR RIM	Cut	880.00 FS	*880.00 FS
26	1		*SUNDRIES	Necessary	250.00 FS	*28.80 FS
27	1		*FRONT HANDLE LIGHT COVER -LH	Cracked	4.64 FS	*4.64 FS
28	2		*FRONT HANDLE UNDERLAY-LH	Not Necessary	8.00 FS	*- FS
29	1		*FRONT WINDOW REGULATOR-LH	Cracked	225.60 FS	*225.60 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)**12,887.24****6,957.36**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY & FRONT PARKING AID	New	480.00	0.00
2	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT DAMAGES	New	700.00	560.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT DOOR AND LHS REAR DOOR TO REPAIR BONNET ,LHS FRONT FENDER AND LHS REAR FENDER .RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	3,850.00	1,500.00
4	TO RESPRAY FRONT BUMPER ,LHS FRONT FENDER ,BONNET ,LHS FRONT DOOR ,LHS REAR DOOR ,LHS WING MIRROR COVER ,DOOR HANDLES AND LHS REAR FENDER	New	5,600.00	1,850.00
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			11,102.00	4,382.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >