

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21005307/KTF3N2**Date:** 09/12/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00185572006

**Claimant Vehicle
No :** PC7284X**Insured Vehicle
No :** SJG3511S

Date of Loss: 27/04/2021

Nature of Claim: TP

Claim
No: SNM21D202455/C2/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **PC7284X**

Make & Model: NISSAN NV350, 2.5 (A)

Engine No: YD25017695B

Reg. Date: 24/05/2018 (Man. Year: 2018)

Chassis No: JN1TC2E26Z0051974

Colour: Silver

Odometer: 111463 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,052.00	12,152.00	2,900.00	19.27
Miscellaneous Items	390.00	390.00	0.00	0.00
Labour	6,660.00	5,770.00	890.00	13.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	22,102.00	18,312.00	3,790.00	17.15
+ GST 7.00/7.00% (\$\$)	1,547.14	1,281.84	265.30	17.15
Nett Amount (\$\$)	23,649.14	19,593.84	4,055.30	17.15

INSPECTION

Date of Assignment:	29/04/2021	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	30/04/2021	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	18.0 days		

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Dec 2021)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC7284X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT BUMPER	Bent	320.00 F	*320.00 F
2	1		*1 PC FRT BUMPER RH SIDE RETAINER	Distorted	85.00 F	*85.00 F
3	1		*1 PC FRT BUMPER RH FOG LAMP GARNISH	Dented	90.00 F	*90.00 F
4	1		*1 PC FRT BUMPER REINFORCEMENT	Repair	290.00 F	*- F
5	1		*1 PC FRT BUMPER CENTRE LOWER GRILLE	Dented	395.00 F	*395.00 F
6	1		*6 PCS FRT BUMPER CLIPS @2/PC	Necessary	12.00 F	*12.00 F
7	1		*1 PC FRT BUMPER RH BRACKET	Distorted	70.00 F	*70.00 F
8	1		*1 PC RH HEADLAMP	Broken	260.00 F	*260.00 F
9	1		*1 PC FRT RH CORNAL PANEL	Bent	220.00 F	*220.00 F
10	1		*1 PC FRT GRILLE	Missing	300.00 F	*300.00 F
11	1		*1 PC FRT GRILLE LOGO	Missing	65.00 F	*65.00 F
12	1		*6 PCS FRT GRILLE CLIPS @2/PC	Necessary	12.00 F	*12.00 F
13	1		*1 PC FRT PANEL	Bent	550.00 F	*550.00 F
14	1		*1 PC FRT PANEL INNER LOWER PANEL	Repair	350.00 F	*- F
15	1		*1 PC FRT WINDSCREEN GLASS WITH MOULDING	Cracked	600.00 F	*600.00 F
16	1		*1 PC FRT WIPER GARNISH	Cracked	140.00 F	*140.00 F
17	1		*1 PC FRT WIPER LINKAGE	Serviceable	250.00 F	*- F
18	1		*1 PC FRT WIPER MOTOR	Serviceable	260.00 F	*- F
19	1		*1 PC ENGINE TURBO COOLER RH	Punctured	1,500.00 F	*1,500.00 F
20	1		*1 PC ENGINE TURBO COOLER COVER	Dented	95.00 F	*95.00 F
21	1		*1 PC DASHBOARD FACIAL	Serviceable	720.00 F	*- F
22	1		*1 PC DASHBOARD CENTRE LOWER GARNISH COVER	Deformed	220.00 F	*220.00 F
23	1		*1 PC METER ASSY	Serviceable	920.00 F	*- F
24	1		*1 PC BRAKE BOOSTER	Dented	1,030.00 F	*1,030.00 F
25	1		*1 PC BRAKE MUSTER PUMP	Dented	220.00 F	*220.00 F
26	1		*1 PC BRAKE BOOSTER BRACKET	Distorted	260.00 F	*260.00 F
27	1		*1 PC STEERING WHEEL SHAFT COVER	Dented	125.00 F	*125.00 F
28	1		*1 PC HORN	Dented	68.00 F	*68.00 F
29	1		*1 PC BRAKE MUSTER PUMP/BOOSTER OIL PIPE	Dented	60.00 F	*60.00 F
30	1		*1 PC BRAKE MUSTER PUMP OIL PIPE SMALL	Dented	65.00 F	*65.00 F
31	1		*1 PC REAR BUMPER	Bent	290.00 F	*290.00 F
32	1		*1 PC REAR BUMPER CENTRE STEP PANEL	Bent	135.00 F	*135.00 F
33	1		*2 PCS REAR BUMPER SIDE RETAINERS @12/PC	Cracked	24.00 F	*24.00 F
34	1		*8 PCS REAR BUMPER CLIPS @2/PC	Necessary	16.00 F	*16.00 F
35	1		*1 PC REAR END PANEL OUTER	Bent	145.00 F	*145.00 F
36	1		*1 PC REAR END PANEL INNER	Bent	260.00 F	*260.00 F
37	1		*1 PC REAR END PANEL INNER TOP BEAM	Bent	55.00 F	*55.00 F
38	1		*1 PC TAILGATE	Bent	1,500.00 F	*1,500.00 F
39	1		*1 PC TAILGATE LOGO	Necessary	55.00 F	*55.00 F
40	1		*1 PC TAILGATE EMBLEM (NV350)	Necessary	65.00 F	*65.00 F
41	1		*1 PC TAILGATE INNER LOCK	Jammed	210.00 F	*210.00 F
42	1		*1 PC TAILGATE INNER RUBBER	Cut	125.00 F	*125.00 F
43	1		*1 PC LH TAILLAMP	Serviceable	110.00 F	*- F
Supplementary #1						
44	1		*1 PC FRT WIPER PANEL	Bent	320.00 F	*320.00 F
45	1		*1 PC BRACKET PEDAL UPPER	Distorted	150.00 F	*150.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*1 PC AIR-CON EVAPORATOR	Cracked	1,850.00 F	*1,850.00 F
47	1		*1 PC CABLE ASSY KEY INTER LOCK	Dented	120.00 F	*120.00 F
48	1		*1 PC TAILGATE INNER LOCK COVER	Dented	32.00 F	*32.00 F
49	1		*1 PC REAR SPARE TYRE GUIDE	Dented	38.00 F	*38.00 F
F=Franchise part.						
Total Parts (S\$)					15,052.00	12,152.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 LTR BRAKE OIL (Necessary)	20.00	20.00
2	1	1 PC ERP BRACKET (Necessary)	20.00	20.00
3	1	1 PC FRT NUMBER PLATE (Dented)	15.00	15.00
4	1	1 PC FRT WINDSCREEN GLASS GUM (Necessary)	40.00	40.00
5	1	1 PC REAR WINDSCREEN GLASS GUM (Necessary)	40.00	40.00
6	1	1 PC STICKER - 70KM/H (Necessary)	10.00	10.00
7	1	1 PC TAILGATE EMERGENCY DOOR STICKER (Necessary)	45.00	45.00
8	1	1 SET REVERSE SENSOR (Dented)	200.00	200.00
Sub Total (\$\$)			390.00	390.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	50.00	50.00
2	REMOVE & REFIX FRT WINDSCREEN GLASS	New	100.00	100.00
3	REMOVE & REFIX REAR WINDSCREEN GLASS	New	100.00	100.00
4	REMOVE & REFIX AIR-CON,CHECK,VACUUM & REFILL GAS	New	100.00	100.00
5	REMOVE & REFIX DASHBOARD,METER ASSY & CHECK WIRING	New	230.00	220.00
6	REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,FRT WIPER ASSY,CORNAL PANEL,TO CUT,WELD & RENEW FRT PANEL,FRT FIRE WALL,TO KNOCK & REPAIR FRT FLOOR BOARD PANEL & REALIGN THE SAME	New	1,400.00	1,200.00
7	REMOVE & REFIX ENGINE TURBO COOLER,REMOVE & REFIX BRAKE MUSTER PUMP & BRACKET,BOOSTER,PIPE & HOSE,HAND BRAKE ASSY AND CHECK BARKE SYSTEM	New	250.00	200.00
8	PUTTY & RESPRAY ON FRT BUMPER,FRT CORNAL PANEL,FRT PANEL,FRT INNER PANEL,FRT FLOOR BOARD PANEL,FRT RH DOOR & ALL FRT AFFECTED AREAS	New	1,200.00	1,000.00
9	REMOVE & REFIX REAR BUMPER ASSY,TAILLAMPS,TAILGATE,LOCK ASSY,REAR WIPER ASSY,THIRD BRAKE LIGHT,TO CUT,WELD & RENEW REAR END PANEL,REAR END PANEL INNER,TO STRAIGHTEN,KNOCK & REPAIR REAR LH CHASSIS,REAR FLOOR BOARD PANEL,REAR BOTH FENDERS,REAR LH TAILLAMP PANEL & REALIGN THE SAME	New	1,200.00	1,100.00
10	REMOVE & REFIX SEAT,CARPET,GARNISH,ETC	New	200.00	120.00
11	REMOVE & REFIX REAR EXHAUST & CHECK LEAKING	New	80.00	60.00
12	PUTTY & RESPRAY ON REAR BOTH SIDE PANELS,TAILGATE,REAR END PANEL OUTER & INNER,REAR FLOOR BOARD PANEL,REAR BUMPER & ALL REAR AFFECTED AREAS	New	1,300.00	1,200.00
13	TO RUSTPROOFING	New	150.00	120.00
14	TO REWRITE ADVERTISEMENT	New	300.00	200.00
Gross Labour Cost (\$\$)			6,660.00	5,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >