

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21005308/RQF3N2**Date:** 07/03/2022**REFERENCE**

Insured/Claimant: MAY ENGINEERING PTE. LTD. Policy No: DMCVSNW00066832000

Date of Loss: 23/03/2021

Nature of Claim: OD

Claim No: SNM21D201713/C01/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN8716X	Engine No:	4JJ11Z1889
Make & Model:	ISUZU NPR85UH5A, 3.0 D (M)	Chassis No:	JAANPR85HF7100422
Reg. Date:	25/08/2015 (Man. Year: 2015)	Odometer:	0 km
Colour:	White		
Engine Capacity:	2999 cc		
Market Value/New Car Price:	S\$49,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85R16	Rear Tyre Size:	195/85R16(D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7/7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	59,891.00	53,251.00	6,640.00	11.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,410.00	3,406.20	1,003.80	22.76
Paintwork Labour	1,226.00	1,204.01	21.99	1.79
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	65,527.00	57,861.21	7,665.79	11.70
Approved Total (Overridden) (\$\$)		45,000.00		
- Excess (\$\$)	0.00	450.00	-450.00	
(\$\$)	65,527.00	44,550.00	20,977.00	32.01
+ GST 7.00/7.00% (\$\$)	4,586.89	3,118.50	1,468.39	32.01
Nett Amount (\$\$)	70,113.89	47,668.50	22,445.39	32.01

INSPECTION

Date of Assignment:	29/04/2021	Present Location:	Goldbell Engineering Pte Ltd (Tuas)
Date Inspected:	30/04/2021	Inspected At:	Goldbell Engineering Pte Ltd (Tuas) 10 Tuas Ave 18 Singapore 638894
Estimated Period of Repair:	12.0 days		

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 07 Mar 2022)	
Parts:	N/A	ISUZU NPR85UH5A 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN8716X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*AIR INTAKE HOSE	Cracked	180.00 F	*180.00 F
2	1	NA	*CAB BODY CONTROL	Bent	350.00 F	*350.00 F
3	1	NA	*CABIN HEAD	Bent	19,800.00 F	*19,800.00 F
4	1	NA	*COMPRESSOR	Serviceable	580.00 F	*- F
5	1	NA	*CONDENSER	Bent	1,300.00 F	*1,300.00 F
6	1	NA	*CTR FRT PANEL STRUT	Bent	750.00 F	*750.00 F
7	1	NA	*FRONT BUMPER	Deformed	360.00 F	*360.00 F
8	1	NA	*FRONT MANUFACT BADGE	Necessary	320.00 F	*320.00 F
9	1	NA	*FRONT NUMBER PLATE	Bent	0.00 F	*35.00 F
10	1	NA	*FRONT PANEL CPL	Buckled	1,150.00 F	*1,150.00 F
11	1	NA	*FRONT PANEL TRIM	Deformed	350.00 F	*350.00 F
12	1	NA	*FRONT ROOF FRAME	Bent	350.00 F	*350.00 F
13	1	NA	*FRONT TORSION BAR	Bent	540.00 F	*540.00 F
14	1	NA	*GRILLE	Missing	256.00 F	*256.00 F
15	1	NA	*L/CVR PANEL SEAL KIT	Necessary	120.00 F	*120.00 F
16	1	NA	*L/D-MIRROR BRACKET	Missing	85.00 F	*85.00 F
17	1	NA	*L/DOOR LOCK CYLINDER	Jammed	150.00 F	*150.00 F
18	1	NA	*L/DOOR MIRROR	Missing	130.00 F	*130.00 F
19	1	NA	*L/DOOR MIRROR ARM	Missing	120.00 F	*120.00 F
20	1	NA	*L/DOOR OUTER HANDLE	Serviceable	130.00 F	*- F
21	1	NA	*L/DOOR SEAL	Necessary	80.00 F	*80.00 F
22	1	NA	*L/DOOR STRIKER	Necessary	80.00 F	*80.00 F
23	1	NA	*L/F BUMPER BRACKET	Bent	165.00 F	*165.00 F
24	1	NA	*L/F BUMPER GUARD	Bent	450.00 F	*450.00 F
25	1	NA	*L/F CORNER PANEL	Cracked	280.00 F	*280.00 F
26	1	NA	*L/F CTR CAB BRACKET	Bent	280.00 F	*280.00 F
27	1	NA	*L/F DOOR CHECK	Serviceable	120.00 F	*- F
28	1	NA	*L/F DOOR FOIL COVER	Serviceable	120.00 F	*- F
29	1	NA	*L/F DOOR FRAME SEAL	Necessary	280.00 F	*280.00 F
30	1	NA	*L/F DOOR TRIM	Cracked	230.00 F	*230.00 F
31	1	NA	*L/F DOOR WINDOW	Broken	580.00 F	*580.00 F
32	1	NA	*L/F HEADLAMP BRACKET	Bent	120.00 F	*120.00 F
33	1	NA	*L/F INN DOOR HANDLE	Serviceable	130.00 F	*- F
34	1	NA	*L/F INN WINDOW MLDG	Necessary	130.00 F	*130.00 F
35	1	NA	*L/F UPP TORSION BAR	Bent	450.00 F	*450.00 F
36	1	NA	*L/F WINDOW CHANNEL	Deformed	150.00 F	*150.00 F
37	1	NA	*L/F WINDOW REGULATOR	Serviceable	280.00 F	*- F
38	1	NA	*L/F WIPER ARM	Bent	125.00 F	*125.00 F
39	1	NA	*L/F WIPER BLADE	Cut	60.00 F	*60.00 F
40	1	NA	*L/HEADLAMP BRACKET	Serviceable	130.00 F	*- F
41	1	NA	*L/INN DOOR LOCK	Jammed	120.00 F	*120.00 F
42	1	NA	*L/INN IMPACT DAMPER	Bent	540.00 F	*540.00 F
43	1	NA	*L/INN WHEELHOUSE CVR	Deformed	380.00 F	*380.00 F
44	1	NA	*L/LOWER DOOR HINGE	Bent	80.00 F	*80.00 F
45	1	NA	*L/LOWER H-LAMP MLDG	Scratched	130.00 F	*130.00 F
46	1	NA	*L/POSITION LAMP	Cracked	350.00 F	*350.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1	NA	*L/R LOCKING	Jammed	350.00 F	*350.00 F
48	1	NA	*L/SIDE FRAME	Bent	2,580.00 F	*2,580.00 F
49	1	NA	*L/SIDE MEMBER	Bent	280.00 F	*280.00 F
50	1	NA	*L/UPPER DOOR HINGE	Bent	80.00 F	*80.00 F
51	1	NA	*L/WIPER SHAFT	Bent	250.00 F	*250.00 F
52	1	NA	*LEFT FRONT DOOR	Buckled	1,250.00 F	*1,250.00 F
53	1	NA	*LEFT HEADLAMP ASSY	Cracked	420.00 F	*420.00 F
54	1	NA	*LOWER FRONT PANEL	Bent	450.00 F	*450.00 F
55	1	NA	*R/CVR PANEL SEAL KIT	Necessary	120.00 F	*120.00 F
56	1	NA	*R/D-MIRROR BRACKET	Missing	85.00 F	*85.00 F
57	1	NA	*R/DOOR LOCK CYLINDER	Jammed	150.00 F	*150.00 F
58	1	NA	*R/DOOR MIRROR	Missing	130.00 F	*130.00 F
59	1	NA	*R/DOOR MIRROR ARM	Missing	120.00 F	*120.00 F
60	1	NA	*R/DOOR SEAL	Necessary	80.00 F	*80.00 F
61	1	NA	*R/DOOR STRIKER	Jammed	80.00 F	*80.00 F
62	1	NA	*R/F BUMPER BRACKET	Bent	165.00 F	*165.00 F
63	1	NA	*R/F CORNER PANEL	Cracked	280.00 F	*280.00 F
64	1	NA	*R/F CTR CAB BRACKET	Bent	280.00 F	*280.00 F
65	1	NA	*R/F DOOR CHECK	Jammed	120.00 F	*120.00 F
66	1	NA	*R/F DOOR FOIL COVER	Serviceable	120.00 F	*- F
67	1	NA	*R/F DOOR FRAME SEAL	Necessary	280.00 F	*280.00 F
68	1	NA	*R/F DOOR TRIM	Cracked	230.00 F	*230.00 F
69	1	NA	*R/F DOOR WINDOW	Broken	580.00 F	*580.00 F
70	1	NA	*R/F HEADLAMP BRACKET	Serviceable	120.00 F	*- F
71	1	NA	*R/F INN DOOR HANDLE	Cracked	130.00 F	*130.00 F
72	1	NA	*R/F INN WINDOW MLDG	Deformed	130.00 F	*130.00 F
73	1	NA	*R/F WINDOW CHANNEL	Deformed	150.00 F	*150.00 F
74	1	NA	*R/F WINDOW REGULATOR	Bent	280.00 F	*280.00 F
75	1	NA	*R/F WIPER ARM	Bent	125.00 F	*125.00 F
76	1	NA	*R/F WIPER BLADE	Cut	60.00 F	*60.00 F
77	1	NA	*R/HEADLAMP BRACKET	Serviceable	130.00 F	*- F
78	1	NA	*R/INN DOOR LOCK	Bent	120.00 F	*120.00 F
79	1	NA	*R/INN IMPACT DAMPER	Bent	540.00 F	*540.00 F
80	1	NA	*R/INN WHEELHOUSE CVR	Serviceable	380.00 F	*- F
81	1	NA	*R/LOWER DOOR HINGE	Bent	80.00 F	*80.00 F
82	1	NA	*R/LOWER H-LAMP MLDG	Cut	130.00 F	*130.00 F
83	1	NA	*R/OUTER DOOR HANDLE	Serviceable	130.00 F	*- F
84	1	NA	*R/POSITION LAMP	Cracked	350.00 F	*350.00 F
85	1	NA	*R/RADIATOR SEAL	Not Necessary	150.00 F	*- F
86	1	NA	*R/R LOCKING	Jammed	350.00 F	*350.00 F
87	1	NA	*R/SIDE FRAME	Bent	2,580.00 F	*2,580.00 F
88	1	NA	*R/SIDE MEMBER	Serviceable	280.00 F	*- F
89	1	NA	*R/UPPER DOOR HINGE	Bent	80.00 F	*80.00 F
90	1	NA	*R/WIPER SHAFT	Serviceable	230.00 F	*- F
91	1	NA	*RADIATOR	Serviceable	1,500.00 F	*- F
92	1	NA	*RADIATOR GRILLE SEAL	Not Necessary	150.00 F	*- F
93	1	NA	*REAR PRESSURE HOSE	Serviceable	280.00 F	*- F
94	1	NA	*REAR SCREEN	Broken	450.00 F	*450.00 F
95	1	NA	*REAR SCREEN SEAL (Npa)	Not Necessary	0.00 F	*- F
96	1	NA	*REAR SCREEN SEAL	Necessary	50.00 F	*50.00 F
97	1	NA	*RIGHT FRONT DOOR	Buckled	1,250.00 F	*1,250.00 F
98	1	NA	*RIGHT HEADLAMP ASSY	Cracked	420.00 F	*420.00 F
99	1	NA	*ROOF	Serviceable	1,380.00 F	*- F
100	1	NA	*UP COWL PANEL GRILLE	Missing	80.00 F	*80.00 F
101	1	NA	*UPPER MOULDING (Npa)	Not Necessary	0.00 F	*- F
102	1	NA	*WASHER CONTAINER CPL	Serviceable	140.00 F	*- F
103	1	NA	*WINDSCREEN	Broken	1,280.00 F	*1,280.00 F
104	1	NA	*WINDSCREEN SEAL	Necessary	350.00 F	*350.00 F
105	1	NA	*WIPER MOTOR	Serviceable	195.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
106	1	NA	*SUNDRY PARTS (Npa)	Not Necessary	0.00 F	*- F
Supplementary #1						
107	1		*STEERING BOX ASSY	Bent	4,500.00 F	*4,500.00 F
F=Franchise part.						
Total Parts (S\$)					59,891.00	53,251.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	1,226.00	1,204.01
<u>Labour Items</u>				
2	Total Panel/Mechanical Labour	New	4,410.00	3,406.20
Gross Labour Cost (\$\$)			5,636.00	4,610.21

Report was unsubmitted during this print-out.

< END OF ESTIMATES >