

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005313/KPA3Q2**Date:** 12/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700007875
Claimant Vehicle No :	SMK9249D	Insured Vehicle No :	SLN8977M
Date of Loss:	27/04/2021	Nature of Claim:	TP
		Claim No:	4534888093SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK9249D	Engine No:	2ZR0D31845
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Chassis No:	JTDZS3EU70J039676
Reg. Date:	29/04/2019 (Man. Year: 2019)	Odometer:	152889 km
Colour:	Metallic Pearl White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Premio 8 mm	Rear Left Side:	Premio 8 mm
Front Right Side:	Premio 8 mm	Rear Right Side:	Premio 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,874.32	950.02	924.30	49.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	420.00	330.00	44.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,624.32	1,370.02	1,254.30	47.80
+ GST 7.00/7.00% (S\$)	183.70	95.90	87.80	47.80
Nett Amount (S\$)	2,808.02	1,465.92	1,342.10	47.80
+ Car Rental (3.0 x S\$84.00/day) (S\$)		252.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,719.92		

INSPECTION

Date of Assignment:	29/04/2021	
Date Inspected:	30/04/2021	Inspected At: City Auto Pte Ltd (HQ) 160 Sin Ming Drive #05-01,, Sin Ming AutoCity, Singapore 575722
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (UPPER)	Repair	556.40 FL	*- FL
2	1		*REAR BUMPER (LOWER)	Dented / Cut	849.90 FL	*849.90 FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	216.80 FL	*216.80 FL
4	8		*REAR BUMPER CLIPS	Not Necessary	36.00 FL	*- FL
5	1		*REVERSE SENSOR	Serviceable	350.00 FS	*- FS
6	1		*BODY STICKER	Necessary	280.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,289.10	1,216.70
- List Item Discount on L Items 25.00/25.00% (S\$)	414.78	266.68
Total Parts (S\$)	1,874.32	950.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REVERSE SENSOR	New	50.00	0.00
2	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS	New	400.00	200.00
3	SPRAY PAINTING ON AFFECTED & REPLACED PARTS	New	300.00	220.00
Gross Labour Cost (\$)			750.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >