

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21005316/BUF3N2**Date:** 25/10/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00061622000

**Claimant Vehicle
No :** SME931H**Insured
Vehicle No :** SKE1331G

Date of Loss: 27/04/2021

Nature of Claim: TP

Claim
No: SNM21D202460/C02/TOHHS**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SME931H**

Make & Model: HONDA FIT, 1.3 (A)

Engine No: HIDDEN

Reg. Date: (Man. Year:)

Chassis No: GD12331265

Colour: Silver

Odometer: 186425 km

Engine Capacity: 1317 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50R15

Rear Tyre Size: 195/50R15

Front Left Side: Yokohama 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,788.00	3,473.36	3,314.64	48.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	1,720.00	1,030.00	37.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,538.00	5,193.36	4,344.64	45.55
Approved Total (Overridden) (\$\$)		4,150.00		
(\$\$)	9,538.00	4,150.00	5,388.00	56.49
+ GST 7.00/7.00% (\$\$)	667.66	290.50	377.16	56.49
Nett Amount (\$\$)	10,205.66	4,440.50	5,765.16	56.49

INSPECTION

Date of Assignment: 20/10/2021

Date Inspected: 30/04/2021 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 8.0 days

Adjuster: Lim Teow Guan**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2021)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME931H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	534.70 FL	*534.70 FL
2	1		*BONNET RH HINGE	Bent	35.10 FL	*35.10 FL
3	1		*BONNET LH HINGE	Bent	35.10 FL	*35.10 FL
4	1		*BONNET LOCK	Not Damaged	45.80 FL	*- FL
5	1		*FRONT BUMPER	Broken	544.60 FL	*544.60 FL
6	1		*FRONT BUMPER NUMBER PLATE GARNISH	Broken	50.70 FL	*50.70 FL
7	1		*FRONT BUMPER LOWER GRILLE	Broken	162.90 FL	*162.90 FL
8	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	13.40 FL	*13.40 FL
9	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	13.40 FL	*13.40 FL
10	1		*FRONT BUMPER REINFORCEMENT	Bent	231.10 FL	*154.80 FL
11	1		*FRONT GRILLE	Broken	181.90 FL	*181.90 FL
12	1		*FRONT GRILLE EMBLEM	Necessary	24.30 FL	*24.30 FL
13	1		*FRONT RH FENDER	Bent	364.80 FL	*364.80 FL
14	1		*FRONT RH FENDER SPLASH SHIELD	Torn	72.90 FL	*72.90 FL
15	1		*SUPPORT PANEL	Bent	594.80 FL	*374.60 FL
16	1		*RH HEADLAMP ASSY	Broken	505.20 FL	*505.20 FL
17	1		*RH HEADLAMP LOWER BRACKET	Dented	25.30 FL	*25.30 FL
18	1		*LH HEADLAMP ASSY	Cut	505.20 FL	*505.20 FL
19	1		*LH HEADLAMP BRACKET	Dented	25.30 FL	*25.30 FL
20	1		*AIRCON CONDENSER	Bent	607.80 FL	*580.00 FL
21	1		*RADIATOR ASSY	Not Damaged	1,670.50 FL	*- FL
22	1		*WIPER GARNISH	Not Damaged	109.50 FL	*- FL
23	1		*FRONT RH DOOR (NPA)	Repair	0.00 FL	*- FL
24	1		*FRONT RH SHOCK ABSORBER	Not Necessary	317.50 FL	*- FL
25	1		*FRONT RH SHOCK ABSORBER TOP MOUNTING	Not Necessary	89.40 FL	*- FL
26	1		*FRONT RH KNUCKLE ARM	Not Necessary	381.90 FL	*- FL
27	1		*FRONT RH WHEEL BEARING	Not Necessary	166.90 FL	*- FL
28	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
29	1		*FRONT BUMPER LOWER SPOILER	Not Damaged	700.00 FS	*- FS
30	1		*FRONT NUMBER PLATE	Broken	70.00 FS	*50.00 FS
31	1		*SET FRONT RH FENDER SPLASH SHIELD CLIPS	Necessary	50.00 FS	*30.00 FS
32	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,250.00	4,314.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,462.00	840.84
Total Parts (\$\$)	6,788.00	3,473.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS,TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	800.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	800.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	60.00	0.00
4	APPLY RUST COATING ON AFFECTED AREAS	New	50.00	0.00
5	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES.TO REFILL AIRCON GAS	New	180.00	120.00
6	REMOVE AND REPLACE RADIATOR,HOSES AND FAN ASSY.TO REFILL RADIATOR COOLANT	New	180.00	0.00
7	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	New	180.00	0.00
8	CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
Gross Labour Cost (\$\$)			2,750.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >