4/6/22, 1:54 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21005317/KPA3Q2

06/04/2022 Date:

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100498395 **Claimant Vehicle** SJJ8289K Insured Vehicle No:

SFU2220L No:

Date of Loss: 26/04/2021 Nature of Claim: TP Claim No: 7053360267SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SJJ8289K

Make & Model: TOYOTA C-HR, 1.2 TURBO LUXURY (A) 8NRU174077 Engine No:

Reg. Date: 16/05/2018 (Man. Year: 2018) Chassis No: JTNKY3BX901006432

Colour: Odometer: 27758 km Metallic Grey

**Engine Capacity:** 1197 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17 Front Left Side: Rear Left Side: Michelin 8 mm Michelin 8 mm Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,490.78	4,196.18	294.60	6.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	550.00	350.00	38.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,390.78	4,746.18	644.60	11.96
+ GST 7.00/7.00% (S\$)	377.35	332.23	45.12	11.96
Nett Amount (S\$)	5,768.13	5,078.41	689.72	11.96

+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$) 214.00 + Doc/Search Fee (S\$) 2.00

> **Nett Liability (S\$)** 5,294.41

**INSPECTION** 

Date of Assignment: 30/04/2021

Cheng Hoe Motor Pte Ltd (AMK)

10 ANG MO KIO IND PARK 2A, #01-04 ANG MO Date Inspected: 11/05/2021 Inspected At:

KIO AUTOPOINT

Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: **CHEW HSIAO TONG** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	397.60 FL	*397.60 FL
2	1		*FRONT BUMPER LOWER BUMPER	Dented / Cut	515.41 FL	*515.41 FL
3	1		*FRONT BUMPER LH SIDE RETAINER	Distorted	118.90 FL	*118.90 FL
4	6		*FRONT BUMPER CLIP	Necessary	27.00 FL	*27.00 FL
5	1		*FRONT BUMPER PDC SENSOR	Serviceable	392.80 FL	*- FL
6	1		*HEADLAMP LH	Cut	4,536.00 FL	*4,536.00 FL
F=Fra	inchise	part. L=ListIter		Sub Total (S\$)	5,987.71	5,594.91
			- List Item Discount on L Items	25.00/25.00% (5\$)	1,496.93	1,398.73
				Total Parts (S\$)	4,490.78	4,196.18
			Report was unsubmitted during th	is print-out.		

Adjuster Report

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	<u>our Items</u>			
1	REMOVE & REFIX FRT BUMPER & ATTACHMENTS ,GRILLE LH HEADLAMP ,KNOCKING & REPAIR FRT PANEL & REALIGN THE SAME	New	400.00	250.00
2	PUTTY & RESPRAY FRT BUMPER & PARKING SENSORS ,FRT LH FENDER & ALL AFFECTED AREAS	New	500.00	300.00
	Gross Labor	ur Cost (S\$)	900.00	550.00
	Report was unsubmitted during this	s print-out.		

< END OF ESTIMATES >