

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/ICS21005318/KQY3Q2  
**Date:** 20/10/2022

### REFERENCE

Handling Insurer: ECICS Limited Policy No:  
**Claimant Vehicle No :** GBH5741X **Insured Vehicle No :** SLF3820G  
 Date of Loss: 20/04/2021 Nature of Claim: TP Claim No: DMPC2100146H/02/CT

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH5741X**  
 Make & Model: NISSAN NV200, 1.6 DX-2 (A) Engine No: HR16119367D  
 Reg. Date: 18/07/2018 (Man. Year: 2018) Chassis No: VM20123114  
 Colour: White Odometer: 27886 km  
 Engine Capacity: 1597 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 165/80R14 Rear Tyre Size: 165/80R14  
 Front Left Side: Toyo 8 mm Rear Left Side: Toyo 6 mm  
 Front Right Side: Toyo 8 mm Rear Right Side: Toyo 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>	
Parts	13,606.90	9,689.90	3,917.00	28.79	
Miscellaneous Items	0.00	0.00	0.00		
Labour	4,890.00	4,120.00	770.00	15.75	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>18,496.90</b>	<b>13,809.90</b>	<b>4,687.00</b>	<b>25.34</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>10,300.00</b>			
	<b>(S\$)</b>	18,496.90	10,300.00	8,196.90	44.31
	<b>+ GST 7.00/7.00% (S\$)</b>	1,294.78	721.00	573.78	44.31
	<b>Nett Amount (S\$)</b>	<b>19,791.68</b>	<b>11,021.00</b>	<b>8,770.68</b>	<b>44.31</b>

### INSPECTION

Date of Assignment: 30/04/2021  
 Date Inspected: 30/04/2021 Inspected At: BLK 8 SIN MING IND ESTATE #01-60/62 SECTOR C SINGAPORE C  
 Estimated Period of Repair: 18.0 days Repairer:City Auto Pte Ltd (HQ)

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

*any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 19 Oct 2022)	
<b>Parts:</b>	N/A	NISSAN NV200 1.6 DX-2 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBH5741X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*BONNET</b>	Buckled	580.00 FN	*580.00 FN
2	2		<b>*BONNET HINGE</b>	Bent / Distorted	170.00 FN	*170.00 FN
3	1		<b>*BONNET LOCK</b>	Distorted	98.00 FN	*98.00 FN
4	2		<b>*FRONT HEADLAMP</b>	Mtg Broken	640.00 FN	*640.00 FN
5	1		<b>*FRONT HEADLAMP LOWER GARNISH</b>	N/S Missing	370.00 FN	*185.00 FN
6	1		<b>*FRONT GRILLE</b>	Missing	325.00 FN	*325.00 FN
7	1		<b>*FRONT GRILLE LOGO</b>	Missing	48.00 FN	*48.00 FN
8	1		<b>*FRONT GRILLE MOULDING</b>	Missing	85.00 FN	*85.00 FN
9	1		<b>*FRONT BUMPER</b>	Bent	385.00 FN	*385.00 FN
10	2		<b>*FRONT BUMPER SIDE RETAINER</b>	Cracked	84.00 FN	*84.00 FN
11	1		<b>*FRONT BUMPER REINFORCEMENT</b>	Bent	425.00 FN	*425.00 FN
12	1		<b>*FRONT BUMPER LOWER GUARD</b>	Missing	145.00 FN	*145.00 FN
13	1		<b>*FRONT BUMPER TOW COVER</b>	Missing	35.00 FN	*35.00 FN
14	1		<b>*FRONT FENDER INNER SHIELD LH</b>	Torn	115.00 FN	*115.00 FN
15	2		<b>*FRONT HEADLAMP PANEL</b>	Bent	116.00 FN	*116.00 FN
16	1		<b>*SUPPORT PANEL</b>	Buckled	450.00 FN	*450.00 FN
17	1		<b>*AIR CON CONDENSER</b>	Punctured	585.00 FN	*585.00 FN
18	1		<b>*RADIATOR ASSY</b>	Bent / Punctured	550.00 FN	*550.00 FN
19	1		<b>*FAN COWLING</b>	Serviceable	185.00 FN	*- FN
20	1		<b>*FAN MOTOR</b>	Serviceable	280.00 FN	*- FN
21	1		<b>*FAN BLADE</b>	Serviceable	90.00 FN	*- FN
22	1		<b>*FRONT WHEEL COVER LH</b>	Cracked	115.00 FN	*115.00 FN
23	1		<b>*FRONT SHOCK ABSORBER LH</b>	Bent	225.00 FN	*225.00 FN
24	1		<b>*FRONT KNUCKLE ARM LH</b>	Bent	285.00 FN	*285.00 FN
25	1		<b>*FRONT LOWER ARM LH</b>	Bent	265.00 FN	*265.00 FN
26	1		<b>*FRONT WHEEL BEARING -LH</b>	Necessary	115.00 FN	*115.00 FN
27	1		<b>*FRONT LINKAGE LH</b>	Serviceable	85.00 FN	*- FN
28	1		<b>*TIE ROD END -LH</b>	Serviceable	90.00 FN	*- FN
29	1		<b>*STEERING RACK END -LH</b>	Serviceable	155.00 FN	*- FN
30	1		<b>*ENGINE UNDER COVER -LH</b>	Missing	180.00 FN	*180.00 FN
31	1		<b>*ENGINE UNDER COVER -RH</b>	Serviceable	180.00 FN	*- FN
32	1		<b>*FUSE BOX COVER -TOP</b>	Cracked	155.00 FN	*155.00 FN
33	1		<b>*FUSE BOX COVER -BOTTOM</b>	Cracked	195.00 FN	*195.00 FN
34	1		<b>*AUTO GEAR BOX (LOCAL REPAIR)</b>	Housing Cracked	1,665.00 FS	*500.00 FS
35	1		<b>*DRIVE SHAFT -LH</b>	Repair	685.00 FN	*- FN
36	1		<b>*FRONT CROSS MEMBER</b>	Serviceable	650.00 FN	*- FN
37	1		<b>*STEERING AIR BAG</b>	Burst	850.00 FN	*850.00 FN
38	1		<b>*PASSENGER AIR BAG</b>	Burst	950.00 FN	*950.00 FN
39	2		<b>*FRONT SEAT BELT</b>	Jammed	770.00 FN	*770.00 FN
40	1		<b>*SRS CONTROL MODULE</b>	Necessary	600.00 FN	*600.00 FN
41	1		<b>*FRONT BRAKE PIPE -LH</b>	Serviceable	195.00 FN	*- FN
42	1		<b>*SET ENGINE MOUNTING</b>	Cracked	485.00 FN	*485.00 FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
43	1		<b>*FRONT RIM LH</b>	Serviceable	250.00 FS	*- FS	
						F=Franchise part. S=SpcNett. N=NettItemDisc.	
					<b>Sub Total (S\$)</b>	<b>14,906.00</b>	<b>10,711.00</b>
					<b>- Nett Item Discount on N Items 10.00/10.00% (S\$)</b>	1,299.10	1,021.10
					<b>Total Parts (S\$)</b>	<b>13,606.90</b>	<b>9,689.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND INSTALL FRONT SUSPENSION	New	250.00	200.00
2	TO CONDUCT WHEEL ALIGNMENT	New	60.00	60.00
3	TO REMOVE AND INSTALL ENGINE AND GEAR BOX TO CARRY OUT REPAIR ON FRONT PORTION	New	300.00	250.00
4	TO REMOVE AND INSTALL AIR BAGS ,SEAT BELT AND SRS CONTROL MODULE	New	250.00	200.00
5	TO RECHARGE AIR CON GAS	New	120.00	100.00
6	TO CHECK AND REPAIR WIRE HARNESS	New	150.00	150.00
7	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS	New	2,500.00	2,000.00
8	SPRAY PAINTING ON AFFECTED & REPLACED PARTS	New	1,200.00	1,100.00
9	TOWING CHARGE	New	60.00	60.00
			<b>Gross Labour Cost (S\$)</b>	<b>4,890.00</b>
				<b>4,120.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >