



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1765J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRT BUMPER ASSY	CRACKED	430.90	430.90
1	FRT FENDER RH	DENTED	588.80	588.80
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	DAY LIGHT-RH	SERVICEABLE	642.50	-
1	FRT BUMPER SIDE GRILLE RH	DEFORMED	93.45	93.45
1	FRT BUMPER SIDE BRACKET RH	SERVICEABLE	35.00	-
1	FRT BUMPER LIP	NOT NECESSARY	35.10	-
1	FRT FENDER EMBLEM	NECESSARY	26.60	26.60
	LESS 20% DISCOUNT		-374.87	-232.35
			1,499.48	929.40
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		800.00	700.00
	SPRAYPAINT.		600.00	500.00
	CHECK WIRING.	NOT NECESSARY	50.00	-
	TUFF KOTE.		50.00	40.00
			1,500.00	1,240.00
	<b>GRAND TOTAL</b>		<b>2,999.48</b>	<b>2,169.40</b>
	<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>2,169.40</b>

Report Ref No. NS/INC21005319/Nqcn2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.